

## 292 NEW FULL SERVICE KIT® SKUs



Walker Product's Full Service Kits® are a totally new concept in selling an engine management sensor solution. This product offering is exclusive to the automotive aftermarket, and has received the MOTOR Top 20 Tools+ Award for it's innovative features that help technicians repair vehicles correctly - the first time. Our Full Service Kits® contain not only the base sensor, but also provide the technician or DIY'er the mating connector and pigtail. We even include the butt splices and heat shrink to ensure a watertight connection.

### Camshaft & Crankshaft Position Sensor FSK®

204 NEW SKUs



**Walker # 235-91002**

1990-2019

Ford, Jaguar, Lincoln

& Mercury

US VIO: 6,892,712

MX VIO: 580,739

### Idle Air Control Valve FSK®

26 NEW SKUs



**Walker # 215-92061**

2001-2008

Ford, Mazda & Mercury

US VIO: 640,180

MX VIO: 56,052

### Knock Sensor FSK®

21 NEW SKUs



**Walker # 242-91055**

2003-2019

Chrysler, Dodge, Fiat, Jeep, Ram & SRT

US VIO: 8,644,875

MX VIO: 563,542

### Throttle Position Sensor FSK®

16 NEW SKUs



**Walker # 200-91240**

1997-2004

Lexus & Toyota

US VIO: 1,612,725

MX VIO: 47,711

### Vehicle Speed Sensor FSK®

15 NEW SKUs



**Walker # 240-91147**

2007-2019

Chrysler, Dodge & Ram

US VIO: 3,022,587

MX VIO: 51,610

### Air Charge Temp Sensor FSK®

10 NEW SKUs



**Walker # 210-91035**

1991-2005

Buick, Cadillac, Chevrolet, Oldsmobile & Pontiac

US VIO: 1,283,854

MX VIO: 191,716

## Throttle Position Sensor

10 NEW SKUs

**Walker # 200-1425**  
2013-2019  
Nissan  
US VIO: 2,927,552  
MX VIO: 12,426



## Wire Set

7 NEW SKUs

**Walker # 924-1552**  
1957-2019  
US VIO: 11,010,594  
MX VIO: 1,433,342

American Motors, Austin Healey, Buick, Cadillac, Checker, Chevrolet, Chrysler, DeLorean, Dodge, Eagle, Ford, GMC, Hyundai, International, Isuzu, Jeep, Mazda, Mercury, Mitsubishi, Nissan, Oldsmobile, Peugeot, Plymouth, Pontiac, Saturn, Studebaker, Subaru, Toyota, Triumph, Volkswagen & Volvo



## O2 Sensor OE

6 NEW SKUs

**Walker # 250-241256**  
2017-2021  
Honda  
US VIO: 677,712  
MX VIO: 12,003



## MAP Sensor

5 NEW SKUs


**Walker # 225-1278**  
2006-2012  
Subaru  
US VIO: 946,400  
MX VIO: 1,308



## Ignition Coil

3 NEW SKUs

**Walker # 920-1090**  
2005-2010  
Hyundai & Kia  
US VIO: 134,009



## O2 Sensor Aftermarket

2 NEW SKUs


**Walker # 350-341032**  
2015-2020  
Volvo  
US VIO: 126,305  
MX VIO: 1,643



## Flex Fuel Sensor

2 NEW SKUs

**Walker # 243-1001**  
2000-2005  
Chevrolet & GMC  
US VIO: 1,884,599  
MX VIO: 76,892



## Knock Sensor

1 NEW SKU

**Walker # 242-1204**  
2002-2010  
Ford, Mazda & Mercury  
US VIO: 769,395  
MX VIO: 95,327



## Fuel Pressure Regulator

1 NEW SKU


**Walker # 255-1163**  
1993-2015  
Nissan  
US VIO: 452,050  
MX VIO: 660,432



## Fuel Injector Throttle Body

1 NEW SKU

**Walker # 550-1000**  
1995-1997  
Chevrolet & GMC  
US VIO: 12,111  
MX VIO: 1,127



## Camshaft Position Sensor

1 NEW SKU

**Walker # 235-2278**  
2013-2017  
Jaguar  
US VIO: 12,045  
MX VIO: 209



MAY 2021

| Part #    | Description - EN             | US VIO    | MX VIO  | Start | End  | Make                                                |
|-----------|------------------------------|-----------|---------|-------|------|-----------------------------------------------------|
| 200-1328  | Throttle Position Sensor     | 7,237     | 11,242  | 1992  | 1994 | Ford & Mercury                                      |
| 200-1344  | Throttle Position Sensor     |           | 6,814   | 2004  | 2005 | Fiat                                                |
| 200-1371  | Throttle Position Sensor     | 3,754     |         | 1989  | 1995 | Porsche                                             |
| 200-1374  | Throttle Position Sensor     | 54,132    | 1,319   | 2000  | 2004 | Honda & Isuzu                                       |
| 200-1379  | Throttle Position Sensor     | 4,398     |         | 1987  | 1992 | Jaguar                                              |
| 200-1394  | Throttle Position Sensor     | 31,093    |         | 2006  | 2008 | Mazda                                               |
| 200-1425  | Throttle Position Sensor     | 2,927,552 | 12,426  | 2013  | 2019 | Nissan                                              |
| 200-1444  | Throttle Position Sensor     | 126,572   | 7,320   | 2004  | 2004 | Ford                                                |
| 200-1457  | Throttle Position Sensor     | 683       |         | 1990  | 1992 | Volkswagen                                          |
| 200-1480  | Throttle Position Sensor     |           | 35,622  | 2012  | 2014 | Dodge                                               |
| 200-91001 | Throttle Position Sensor FSK | 24,196    | 234     | 1982  | 1991 | Cadillac, Dodge, Eagle,<br>Jeep & Renault           |
| 200-91060 | Throttle Position Sensor FSK | 320,784   | 65,484  | 1994  | 2003 | Ford, Mazda & Mercury                               |
| 200-91090 | Throttle Position Sensor FSK | 115,170   | 29,712  | 1996  | 1998 | Ford & Mercury                                      |
| 200-91096 | Throttle Position Sensor FSK | 778,105   | 63,310  | 1997  | 2002 | Dodge & Jeep                                        |
| 200-91099 | Throttle Position Sensor FSK | 449,224   | 64,301  | 1998  | 2010 | Chrysler & Dodge                                    |
| 200-91101 | Throttle Position Sensor FSK | 141,134   | 81,297  | 1998  | 2005 | Chrysler, Dodge & Plymouth                          |
| 200-91104 | Throttle Position Sensor FSK | 91,445    | 19,463  | 1998  | 2004 | Chrysler, Dodge & Plymouth                          |
| 200-91105 | Throttle Position Sensor FSK | 1,281,096 | 102,688 | 1998  | 2007 | Chrysler, Dodge & Plymouth                          |
| 200-91237 | Throttle Position Sensor FSK | 1,479,552 | 52,024  | 1997  | 2006 | Chevrolet, Pontiac, Scion<br>& Toyota               |
| 200-91240 | Throttle Position Sensor FSK | 1,612,725 | 47,711  | 1997  | 2004 | Lexus & Toyota                                      |
| 200-91326 | Throttle Position Sensor FSK | 53,117    | 44,618  | 1991  | 1997 | Saturn                                              |
| 200-91337 | Throttle Position Sensor FSK | 100,935   | 14,209  | 2000  | 2002 | Saturn                                              |
| 200-91423 | Throttle Position Sensor FSK | 64,396    | 10,186  | 2002  | 2007 | Mitsubishi                                          |
| 200-91440 | Throttle Position Sensor FSK | 47,845    | 17,286  | 2003  | 2003 | Ford                                                |
| 200-91448 | Throttle Position Sensor FSK | 1,986     | 3,177   | 1980  | 1982 | Buick, Cadillac, Chevrolet,<br>Oldsmobile & Pontiac |
| 200-91453 | Throttle Position Sensor FSK | 22,873    | 438     | 1994  | 1995 | Chevrolet                                           |
| 210-91007 | Air Charge Temp Sensor FSK   | 51,992    | 28,153  | 1986  | 1996 | Chrysler, Dodge & Plymouth                          |
| 210-91023 | Air Charge Temp Sensor FSK   |           | 58,235  | 1993  | 2003 | Volkswagen                                          |
| 210-91028 | Air Charge Temp Sensor FSK   |           | 19,625  | 1996  | 1997 | Chevrolet                                           |
| 210-91029 | Air Charge Temp Sensor FSK   | 35,087    | 35,717  | 1995  | 2002 | Volkswagen                                          |
| 210-91035 | Air Charge Temp Sensor FSK   | 1,283,854 | 191,716 | 1991  | 2005 | Buick, Cadillac, Chevrolet,<br>Oldsmobile & Pontiac |
| 210-91038 | Air Charge Temp Sensor FSK   | 384,581   |         | 1995  | 2010 | Hyundai & Kia                                       |
| 210-91051 | Air Charge Temp Sensor FSK   | 230,911   | 27,545  | 1997  | 2006 | Audi & Volkswagen                                   |
| 210-91052 | Air Charge Temp Sensor FSK   | 625,655   | 19,411  | 1995  | 2006 | BMW & Land Rover                                    |
| 210-91056 | Air Charge Temp Sensor FSK   | 113,661   | 9,191   | 1999  | 2008 | Chevrolet & Daewoo                                  |
| 210-91057 | Air Charge Temp Sensor FSK   | 4,399     | 54      | 1996  | 1997 | Porsche                                             |
| 215-91021 | Idle Air Control Valve FSK   | 90,948    | 16,562  | 1995  | 2002 | Acura, Chevrolet, GMC, Honda,<br>Isuzu & Oldsmobile |
| 215-91061 | Idle Air Control Valve FSK   | 95,807    | 176,026 | 1993  | 2002 | Volkswagen                                          |
| 215-91062 | Idle Air Control Valve FSK   | 260       | 46      | 1992  | 1994 | Volkswagen                                          |
| 215-91074 | Idle Air Control Valve FSK   | 314,632   | 49,706  | 1991  | 1997 | Jeep                                                |
| 215-91075 | Idle Air Control Valve FSK   | 191,576   | 60,031  | 1995  | 2002 | Saturn                                              |
| 215-91077 | Idle Air Control Valve FSK   |           |         | 1998  | 2009 | Volkswagen                                          |
| 215-91078 | Idle Air Control Valve FSK   | 413,690   | 82,548  | 2002  | 2005 | Chevrolet, Oldsmobile, Pontiac<br>& Saturn          |
| 215-91079 | Idle Air Control Valve FSK   | 147       | 42      | 1995  | 1996 | Chevrolet & GMC                                     |
| 215-92012 | Idle Air Control Valve FSK   | 31,455    | 13,538  | 1991  | 1993 | Ford                                                |
| 215-92016 | Idle Air Control Valve FSK   | 12,995    | 1,070   | 1995  | 1996 | Ford                                                |
| 215-92020 | Idle Air Control Valve FSK   | 11,463    | 12,124  | 1992  | 1995 | Ford & Mercury                                      |

| Part #    | Description - EN               | US VIO    | MX VIO  | Start | End  | Make                                                                         |
|-----------|--------------------------------|-----------|---------|-------|------|------------------------------------------------------------------------------|
| 215-92025 | Idle Air Control Valve FSK     | 106,019   | 71,775  | 1996  | 1999 | Ford, Mercury                                                                |
| 215-92041 | Idle Air Control Valve FSK     | 55,927    | 71,508  | 1997  | 1999 | Ford & Mercury                                                               |
| 215-92061 | Idle Air Control Valve FSK     | 640,180   | 56,052  | 2001  | 2008 | Ford, Mazda & Mercury                                                        |
| 215-92062 | Idle Air Control Valve FSK     | 223,790   | 122,811 | 1999  | 2004 | Ford & Mercury                                                               |
| 215-92063 | Idle Air Control Valve FSK     | 310,512   | 43,393  | 2000  | 2006 | Ford, Mazda & Mercury                                                        |
| 215-92068 | Idle Air Control Valve FSK     | 355,793   | 46,165  | 2002  | 2007 | Ford & Mercury                                                               |
| 215-92070 | Idle Air Control Valve FSK     | 227,904   | 25,233  | 2002  | 2004 | Ford                                                                         |
| 215-92075 | Idle Air Control Valve FSK     | 199       | 289     | 1995  | 1995 | Ford                                                                         |
| 215-92079 | Idle Air Control Valve FSK     | 54,187    | 4,817   | 2000  | 2003 | Ford & Lincoln                                                               |
| 215-92080 | Idle Air Control Valve FSK     | 128,332   | 9,904   | 2002  | 2004 | Ford                                                                         |
| 215-92083 | Idle Air Control Valve FSK     | 59,843    | 4,867   | 2003  | 2004 | Ford                                                                         |
| 215-92086 | Idle Air Control Valve FSK     | 52,688    | 11,319  | 2000  | 2000 | Ford & Mercury                                                               |
| 215-92088 | Idle Air Control Valve FSK     | 53,810    | 41,690  | 1999  | 2001 | Ford                                                                         |
| 215-92105 | Idle Air Control Valve FSK     | 106,373   | 73,461  | 2002  | 2009 | Ford                                                                         |
| 215-92107 | Idle Air Control Valve FSK     | 1,691     | 6,719   | 1995  | 1995 | Ford & Mercury                                                               |
| 225-1117  | MAP Sensor                     | 25        | 6       | 2000  | 2000 | Ford                                                                         |
| 225-1190  | MAP Sensor                     | 18,916    | 3,360   | 2004  | 2004 | Mitsubishi                                                                   |
| 225-1218  | MAP Sensor                     | 52,298    | 382     | 2008  | 2015 | Smart                                                                        |
| 225-1278  | MAP Sensor                     | 946,400   | 1,308   | 2006  | 2012 | Subaru                                                                       |
| 225-1318  | MAP Sensor                     | 74,791    | 225     | 2014  | 2019 | Cadillac                                                                     |
| 235-2278  | Camshaft Position Sensor       | 12,045    | 209     | 2013  | 2017 | Jaguar                                                                       |
| 235-91002 | Camshaft Position Sensor FSK   | 6,892,712 | 580,739 | 1990  | 2019 | Ford, Jaguar, Lincoln<br>& Mercury                                           |
| 235-91012 | Crankshaft Position Sensor FSK | 1,846     | 0       | 1985  | 1988 | Buick, Oldsmobile & Pontiac                                                  |
| 235-91016 | Crankshaft Position Sensor FSK | 55,612    | 55,906  | 1980  | 1991 | Ford, Lincoln & Mercury                                                      |
| 235-91018 | Crankshaft Position Sensor FSK | 274,207   | 227,763 | 1991  | 2004 | Ford & Mercury                                                               |
| 235-91020 | Crankshaft Position Sensor FSK | 114,472   | 51,406  | 1993  | 1999 | Cadillac, Oldsmobile<br>& Shelby                                             |
| 235-91033 | Crankshaft Position Sensor FSK | 17,753    | 1,218   | 2001  | 2006 | Mitsubishi                                                                   |
| 235-91034 | Crankshaft Position Sensor FSK | 69,687    | 85,026  | 2008  | 2011 | Chevrolet, Pontiac & Saturn                                                  |
| 235-91039 | Camshaft Position Sensor FSK   | 550       | 233     | 1997  | 1997 | Cadillac                                                                     |
| 235-91041 | Camshaft Position Sensor FSK   | 422,291   | 31,556  | 2011  | 2019 | Ford                                                                         |
| 235-91042 | Camshaft Position Sensor FSK   | 72,176    | 9,262   | 1998  | 2005 | Cadillac & Saturn                                                            |
| 235-91044 | Crankshaft Position Sensor FSK | 69,429    | 1,461   | 2003  | 2011 | Cadillac, Chevrolet, Saab<br>& Saturn                                        |
| 235-91045 | Crankshaft Position Sensor FSK | 20,597    | 2,007   | 2002  | 2003 | Chevrolet & Saturn                                                           |
| 235-91049 | Crankshaft Position Sensor FSK | 4,033     | 126     | 1992  | 1998 | Audi                                                                         |
| 235-91051 | Camshaft Position Sensor FSK   | 71,146    | 188,925 | 1999  | 2014 | Dodge, Hyundai & Kia                                                         |
| 235-91057 | Crankshaft Position Sensor FSK | 5,439,755 | 252,040 | 1997  | 2009 | Avanti, Buick, Cadillac,<br>Chevrolet, GMC, Hummer,<br>Isuzu, Pontiac & Saab |
| 235-91065 | Camshaft Position Sensor FSK   | 274,207   | 240,911 | 1991  | 2007 | Ford & Mercury                                                               |
| 235-91067 | Camshaft Position Sensor FSK   | 984,418   | 342,303 | 1997  | 2012 | Ford                                                                         |
| 235-91070 | Camshaft Position Sensor FSK   | 1,350,164 | 274,424 | 1995  | 2008 | Ford, Mazda & Mercury                                                        |
| 235-91079 | Crankshaft Position Sensor FSK | 0         | 353,074 | 1994  | 2004 | Chevrolet                                                                    |
| 235-91099 | Camshaft Position Sensor FSK   | 17,154    | 1,483   | 2002  | 2006 | Jeep                                                                         |
| 235-91105 | Camshaft Position Sensor FSK   | 196,173   | 7,289   | 2006  | 2007 | Buick, Chevrolet, GMC,<br>Hummer, Isuzu & Saab                               |
| 235-91107 | Camshaft Position Sensor FSK   | 266,002   | 9,509   | 2004  | 2006 | Chrysler & Dodge                                                             |
| 235-91119 | Crankshaft Position Sensor FSK | 607,737   | 45,789  | 2004  | 2007 | Buick, Chevrolet, Pontiac<br>& Saturn                                        |
| 235-91122 | Camshaft Position Sensor FSK   | 40,869    | 17,462  | 1998  | 2003 | Chevrolet & Suzuki                                                           |

**MAY 2021**

| Part #    | Description - EN               | US VIO    | MX VIO  | Start | End  | Make                                                           |
|-----------|--------------------------------|-----------|---------|-------|------|----------------------------------------------------------------|
| 235-91123 | Camshaft Position Sensor FSK   | 1,303,731 | 135,945 | 1998  | 2007 | Chrysler, Dodge, Jeep & Plymouth                               |
| 235-91124 | Camshaft Position Sensor FSK   | 122,213   | 40,750  | 1997  | 2014 | Chrysler, Dodge, Eagle & Mitsubishi                            |
| 235-91129 | Cam/Crank Position Sensor FSK  | 8,888     | 10,097  | 1995  | 1998 | Mercury                                                        |
| 235-91130 | Crankshaft Position Sensor FSK | 573,264   | 145,894 | 1993  | 2008 | Ford, Mazda & Mercury                                          |
| 235-91132 | Crankshaft Position Sensor FSK | 25,154    | 3,709   | 2000  | 2005 | Saturn                                                         |
| 235-91133 | Crankshaft Position Sensor FSK | 223,841   | 17,702  | 2000  | 2005 | Cadillac, Oldsmobile, Pontiac & Shelby                         |
| 235-91142 | Crankshaft Position Sensor FSK | 160,094   | 68,924  | 1995  | 2000 | Infiniti & Nissan                                              |
| 235-91149 | Camshaft Position Sensor FSK   | 103,210   | 2,659   | 2000  | 2004 | Infiniti, Nissan                                               |
| 235-91150 | Cam/Crank Position Sensor FSK  | 1,995,119 | 56,052  | 2002  | 2020 | Infiniti & Nissan                                              |
| 235-91153 | Crankshaft Position Sensor FSK | 1,555,590 | 44,367  | 2006  | 2011 | Buick, Chevrolet, Pontiac & Saturn                             |
| 235-91158 | Camshaft Position Sensor FSK   | 1,037,994 | 37,609  | 2006  | 2009 | Buick, Chevrolet, Pontiac & Saturn                             |
| 235-91166 | Crankshaft Position Sensor FSK | 8,988     | 0       | 1993  | 1999 | Dodge & Mitsubishi                                             |
| 235-91180 | Camshaft Position Sensor FSK   | 154,452   | 5,407   | 2004  | 2006 | Buick & Cadillac                                               |
| 235-91181 | Crankshaft Position Sensor FSK | 70,248    | 3,588   | 2000  | 2006 | Dodge & Hyundai                                                |
| 235-91183 | Crankshaft Position Sensor FSK | 49,031    | 14,658  | 1999  | 2005 | Chrysler, Dodge & Mitsubishi                                   |
| 235-91184 | Camshaft Position Sensor FSK   | 223,841   | 17,702  | 2000  | 2005 | Cadillac, Oldsmobile & Pontiac                                 |
| 235-91185 | Crankshaft Position Sensor FSK | 166,011   | 6,270   | 1995  | 2001 | Infiniti & Nissan                                              |
| 235-91191 | Camshaft Position Sensor FSK   | 70,248    | 6,940   | 2000  | 2009 | Dodge & Hyundai                                                |
| 235-91194 | Cam/Crank Position Sensor FSK  | 206,742   | 6,080   | 2004  | 2009 | Buick, Cadillac & Saab                                         |
| 235-91196 | Camshaft Position Sensor FSK   | 219,897   | 44,526  | 2004  | 2017 | Mitsubishi                                                     |
| 235-91199 | Camshaft Position Sensor FSK   | 36,902    | 3,088   | 2004  | 2008 | Chevrolet & Suzuki                                             |
| 235-91202 | Crankshaft Position Sensor FSK | 1,736     | 12,697  | 1994  | 1998 | Eagle & Mitsubishi                                             |
| 235-91206 | Camshaft Position Sensor FSK   | 582,216   | 18,307  | 1999  | 2006 | BMW                                                            |
| 235-91211 | Camshaft Position Sensor FSK   | 4,018,119 | 80,438  | 2006  | 2017 | Buick, Chevrolet, GMC, Pontiac, Saab & Saturn                  |
| 235-91215 | Crankshaft Position Sensor FSK | 1,848     | 0       | 1997  | 1999 | Hyundai                                                        |
| 235-91216 | Crankshaft Position Sensor FSK | 16,508    | 0       | 1995  | 2001 | Hyundai                                                        |
| 235-91218 | Crankshaft Position Sensor FSK | 20,502    | 0       | 1995  | 2002 | Kia                                                            |
| 235-91219 | Crankshaft Position Sensor FSK | 574,318   | 69,061  | 1996  | 2007 | Ford & Mercury                                                 |
| 235-91222 | Camshaft Position Sensor FSK   | 319,953   | 72,083  | 1996  | 2006 | Audi, Seat & Volkswagen                                        |
| 235-91228 | Crankshaft Position Sensor FSK | 68,036    | 21,004  | 2001  | 2005 | Chrysler, Dodge & Mitsubishi                                   |
| 235-91230 | Crankshaft Position Sensor FSK | 86,405    | 0       | 2003  | 2006 | Kia                                                            |
| 235-91233 | Camshaft Position Sensor FSK   | 67,474    | 0       | 1999  | 2005 | Mazda                                                          |
| 235-91234 | Camshaft Position Sensor FSK   | 5,214,157 | 117,745 | 2004  | 2019 | Buick, Cadillac, Chevrolet, GMC, Hummer, Isuzu, Pontiac & Saab |
| 235-91241 | Crankshaft Position Sensor FSK | 664,244   | 132,933 | 1996  | 2008 | Ford, Jaguar, Lincoln & Mercury                                |
| 235-91256 | Camshaft Position Sensor FSK   | 394,179   | 0       | 1999  | 2010 | Hyundai & Kia                                                  |
| 235-91257 | Crankshaft Position Sensor FSK | 52,107    | 0       | 1999  | 2006 | Hyundai & Kia                                                  |
| 235-91265 | Crankshaft Position Sensor FSK | 87,894    | 0       | 2001  | 2005 | Hyundai & Kia                                                  |
| 235-91277 | Crankshaft Position Sensor FSK | 965,955   | 26,922  | 2005  | 2019 | Nissan & Suzuki                                                |
| 235-91281 | Camshaft Position Sensor FSK   | 870,539   | 1,265   | 2006  | 2016 | Hyundai & Kia                                                  |
| 235-91293 | Camshaft Position Sensor FSK   | 290,848   | 52,347  | 1994  | 2001 | Ford & Mazda                                                   |
| 235-91296 | Camshaft Position Sensor FSK   | 448,803   | 29,416  | 2003  | 2009 | Ford, Lincoln, Mazda & Mercury                                 |
| 235-91303 | Crankshaft Position Sensor FSK | 19,403    | 4,174   | 2000  | 2004 | Volvo                                                          |
| 235-91307 | Crankshaft Position Sensor FSK | 9,517     | 0       | 1987  | 2001 | Kia & Volvo                                                    |
| 235-91308 | Camshaft Position Sensor FSK   | 52,319    | 1,039   | 1994  | 2000 | Mercedes-Benz                                                  |
| 235-91310 | Crankshaft Position Sensor FSK | 111,167   | 413,210 | 2004  | 2018 | Chevrolet & Pontiac                                            |

| Part #    | Description - EN               | US VIO    | MX VIO | Start | End  | Make                                                         |
|-----------|--------------------------------|-----------|--------|-------|------|--------------------------------------------------------------|
| 235-91313 | Camshaft Position Sensor FSK   | 102,194   | 1,627  | 2005  | 2006 | Jeep                                                         |
| 235-91316 | Crankshaft Position Sensor FSK | 12,984    | 0      | 2003  | 2003 | Mitsubishi                                                   |
| 235-91320 | Camshaft Position Sensor FSK   | 448,803   | 29,416 | 2003  | 2009 | Ford, Lincoln, Mazda & Mercury                               |
| 235-91321 | Crankshaft Position Sensor FSK | 68,266    | 1,605  | 1995  | 2013 | BMW                                                          |
| 235-91322 | Crankshaft Position Sensor FSK | 1,004,414 | 2,978  | 2005  | 2015 | Dodge, Freightliner, Jeep & Mercedes-Benz                    |
| 235-91324 | Camshaft Position Sensor FSK   | 84,945    | 2,659  | 1998  | 2004 | Acura, Honda & Isuzu                                         |
| 235-91326 | Crankshaft Position Sensor FSK | 51,993    | 9,553  | 1996  | 1997 | Buick, Cadillac, Chevrolet & Pontiac                         |
| 235-91334 | Camshaft Position Sensor FSK   | 87,614    | 18,310 | 1991  | 2006 | Ford, Lincoln & Mercury                                      |
| 235-91335 | Camshaft Position Sensor FSK   | 822,541   | 9,211  | 2008  | 2011 | Chrysler, Dodge & Jeep                                       |
| 235-91336 | Camshaft Position Sensor FSK   | 7,941     | 0      | 1992  | 1995 | BMW                                                          |
| 235-91340 | Camshaft Position Sensor FSK   | 64,396    | 10,186 | 2002  | 2007 | Mitsubishi                                                   |
| 235-91345 | Crankshaft Position Sensor FSK | 176,309   | 61,457 | 1996  | 2001 | Ford, Laforza & Mercury                                      |
| 235-91349 | Crankshaft Position Sensor FSK | 950       | 0      | 1999  | 2002 | Daewoo                                                       |
| 235-91353 | Crankshaft Position Sensor FSK | 905,884   | 1,265  | 2006  | 2019 | Genesis, Hyundai & Kia                                       |
| 235-91356 | Crankshaft Position Sensor FSK | 67,845    | 1,977  | 2001  | 2003 | Infiniti & Nissan                                            |
| 235-91369 | Camshaft Position Sensor FSK   | 5,851,597 | 98,247 | 2007  | 2019 | Ford, Lincoln, Mazda & Mercury                               |
| 235-91372 | Crankshaft Position Sensor FSK | 5,301,293 | 97,716 | 2007  | 2019 | Ford, Lincoln, Mazda & Mercury                               |
| 235-91376 | Camshaft Position Sensor FSK   | 1,367,675 | 9,615  | 2000  | 2019 | Chrysler, Dodge, Freightliner & Mercedes-Benz                |
| 235-91381 | Camshaft Position Sensor FSK   | 827,915   | 1,222  | 2004  | 2015 | Saab & Subaru                                                |
| 235-91382 | Camshaft Position Sensor FSK   | 227,503   | 22,357 | 2006  | 2011 | Dodge, Hyundai & Kia                                         |
| 235-91383 | Camshaft Position Sensor FSK   | 60,595    | 4,857  | 1999  | 2014 | Mazda                                                        |
| 235-91385 | Crankshaft Position Sensor FSK | 63,535    | 0      | 2003  | 2006 | Hyundai & Kia                                                |
| 235-91389 | Crankshaft Position Sensor FSK | 19,767    | 2,522  | 1997  | 2005 | Mitsubishi                                                   |
| 235-91390 | Crankshaft Position Sensor FSK | 24,474    | 0      | 1985  | 1995 | Volvo                                                        |
| 235-91406 | Crankshaft Position Sensor FSK | 19,608    | 118    | 1991  | 1995 | BMW                                                          |
| 235-91409 | Crankshaft Position Sensor FSK | 10,476    | 12,038 | 1994  | 1999 | Chrysler, Eagle & Mitsubishi                                 |
| 235-91410 | Camshaft Position Sensor FSK   | 16,160    | 0      | 1996  | 2001 | Hyundai                                                      |
| 235-91411 | Crankshaft Position Sensor FSK | 40,769    | 8,594  | 1991  | 2002 | Lincoln                                                      |
| 235-91419 | Crankshaft Position Sensor FSK | 638       | 0      | 1997  | 1999 | Mitsubishi                                                   |
| 235-91422 | Crankshaft Position Sensor FSK | 11,601    | 0      | 1997  | 2001 | Mitsubishi                                                   |
| 235-91423 | Crankshaft Position Sensor FSK | 27,365    | 41,001 | 1994  | 2002 | Infiniti & Nissan                                            |
| 235-91424 | Camshaft Position Sensor FSK   | 950       | 0      | 1999  | 2002 | Daewoo                                                       |
| 235-91428 | Camshaft Position Sensor FSK   | 85,998    | 655    | 2001  | 2009 | Subaru                                                       |
| 235-91429 | Crankshaft Position Sensor FSK | 129,257   | 704    | 2006  | 2010 | Hyundai & Kia                                                |
| 235-91431 | Camshaft Position Sensor FSK   | 116,244   | 548    | 2002  | 2008 | Mini                                                         |
| 235-91433 | Crankshaft Position Sensor FSK | 212,557   | 24,572 | 2008  | 2020 | Mitsubishi                                                   |
| 235-91436 | Camshaft Position Sensor FSK   | 17,523    | 0      | 2002  | 2004 | Kia                                                          |
| 235-91440 | Crankshaft Position Sensor FSK | 459       | 0      | 1993  | 1996 | Eagle & Mitsubishi                                           |
| 235-91445 | Crankshaft Position Sensor FSK | 19,648    | 0      | 1987  | 1993 | BMW                                                          |
| 235-91447 | Crankshaft Position Sensor FSK | 10,453    | 690    | 2003  | 2006 | Mitsubishi                                                   |
| 235-91448 | Camshaft Position Sensor FSK   | 715,261   | 5,396  | 1996  | 2019 | Chrysler, Dodge, Freightliner, Jeep, Mercedes-Benz & Porsche |
| 235-91450 | Crankshaft Position Sensor FSK | 6,144     | 0      | 1988  | 1995 | BMW                                                          |
| 235-91451 | Crankshaft Position Sensor FSK | 10,554    | 4      | 1998  | 2000 | Chevrolet & GMC                                              |
| 235-91462 | Camshaft Position Sensor FSK   | 129,257   | 704    | 2006  | 2010 | Hyundai & Kia                                                |
| 235-91463 | Camshaft Position Sensor FSK   | 129,257   | 704    | 2006  | 2010 | Hyundai & Kia                                                |
| 235-91465 | Crankshaft Position Sensor FSK | 5,254     | 11,068 | 1996  | 2000 | Volkswagen                                                   |
| 235-91467 | Camshaft Position Sensor FSK   | 2,228     | 0      | 1995  | 1999 | Hyundai                                                      |
| 235-91468 | Camshaft Position Sensor FSK   | 1,094,386 | 18,906 | 2011  | 2019 | Ford                                                         |
| 235-91470 | Crankshaft Position Sensor FSK | 3,526     | 0      | 1993  | 1995 | BMW                                                          |

MAY 2021

| Part #    | Description - EN               | US VIO    | MX VIO  | Start | End  | Make                                   |
|-----------|--------------------------------|-----------|---------|-------|------|----------------------------------------|
| 235-91472 | Crankshaft Position Sensor FSK | 15,099    | 284     | 2003  | 2005 | Land Rover                             |
| 235-91473 | Cam/Crank Position Sensor FSK  | 863       | 0       | 1988  | 1993 | BMW                                    |
| 235-91475 | Crankshaft Position Sensor FSK | 13,268    | 389     | 2000  | 2003 | BMW                                    |
| 235-91480 | Camshaft Position Sensor FSK   | 4,033     | 126     | 1992  | 1998 | Audi                                   |
| 235-91487 | Camshaft Position Sensor FSK   | 803       | 0       | 1995  | 1995 | BMW                                    |
| 235-91489 | Camshaft Position Sensor FSK   | 3,488     | 4,345   | 1994  | 1997 | Chevrolet, Oldsmobile & Pontiac        |
| 235-91490 | Camshaft Position Sensor FSK   | 1,773,779 | 31,556  | 2013  | 2019 | Ford                                   |
| 235-91495 | Crankshaft Position Sensor FSK | 823       | 0       | 1994  | 1996 | Mitsubishi                             |
| 235-91499 | Camshaft Position Sensor FSK   | 2,683     | 0       | 2005  | 2007 | Land Rover                             |
| 235-91502 | Camshaft Position Sensor FSK   | 48,613    | 0       | 2009  | 2019 | Hyundai & Kia                          |
| 235-91503 | Camshaft Position Sensor FSK   | 3,543     | 0       | 1991  | 1992 | BMW                                    |
| 235-91504 | Crankshaft Position Sensor FSK | 1,167     | 0       | 1992  | 1993 | BMW                                    |
| 235-91506 | Cam/Crank Position Sensor FSK  | 20        | 0       | 1990  | 1998 | Audi                                   |
| 235-91514 | Camshaft Position Sensor FSK   | 126,508   | 2,235   | 2005  | 2019 | Porsche                                |
| 235-91516 | Crankshaft Position Sensor FSK | 1,733     | 0       | 1984  | 1997 | Audi                                   |
| 235-91520 | Crankshaft Position Sensor FSK | 373       | 0       | 1991  | 1995 | Hyundai                                |
| 235-91536 | Cam/Crank Position Sensor FSK  | 775       | 0       | 1984  | 1988 | Audi                                   |
| 235-91539 | Crankshaft Position Sensor FSK | 1,218     | 0       | 1990  | 1992 | Alfa Romeo                             |
| 235-91551 | Crankshaft Position Sensor FSK | 1,297     | 299     | 1992  | 1995 | Volkswagen                             |
| 235-91552 | Camshaft Position Sensor FSK   | 1,058,510 | 2,986   | 2011  | 2019 | Ford                                   |
| 235-91554 | Camshaft Position Sensor FSK   | 165,120   | 477     | 2008  | 2017 | Subaru                                 |
| 235-91559 | Crankshaft Position Sensor FSK | 42,091    | 189,779 | 1993  | 1999 | Infiniti & Nissan                      |
| 235-91564 | Crankshaft Position Sensor FSK | 2,012     | 1,026   | 1996  | 1998 | Mitsubishi                             |
| 235-91565 | Crankshaft Position Sensor FSK | 17,523    | 0       | 2002  | 2004 | Kia                                    |
| 235-91567 | Crankshaft Position Sensor FSK | 26,604    | 17,906  | 1994  | 1996 | Buick, Chevrolet, Oldsmobile & Pontiac |
| 235-91569 | Camshaft Position Sensor FSK   | 195,111   | 36,526  | 2006  | 2013 | Mazda                                  |
| 235-91572 | Camshaft Position Sensor FSK   | 30,766    | 5,748   | 2000  | 2003 | Lincoln                                |
| 235-91578 | Camshaft Position Sensor FSK   | 94,791    | 10,720  | 2008  | 2011 | Mitsubishi                             |
| 235-91579 | Cam/Crank Position Sensor FSK  | 22,582    | 9,590   | 2007  | 2011 | Mitsubishi                             |
| 235-91580 | Crankshaft Position Sensor FSK | 3         | 0       | 1996  | 1996 | Mitsubishi                             |
| 235-91581 | Camshaft Position Sensor FSK   | 102,783   | 651     | 2002  | 2019 | Jeep, Ram                              |
| 235-91588 | Crankshaft Position Sensor FSK | 28        | 0       | 1996  | 1998 | Hyundai                                |
| 235-91591 | Camshaft Position Sensor FSK   | 3,759     | 655     | 1998  | 2000 | Chevrolet                              |
| 235-91594 | Crankshaft Position Sensor FSK | 36,744    | 379     | 2009  | 2013 | Chevrolet                              |
| 235-91595 | Crankshaft Position Sensor FSK | 0         | 338,985 | 2002  | 2012 | Chevrolet                              |
| 235-91597 | Crankshaft Position Sensor FSK | 260,322   | 8,658   | 1999  | 2010 | Ford, Jaguar, Land Rover & Lincoln     |
| 235-91599 | Crankshaft Position Sensor FSK | 21,758    | 39,959  | 1994  | 2002 | Infiniti & Nissan                      |
| 235-91600 | Camshaft Position Sensor FSK   | 32,978    | 1,015   | 2004  | 2006 | Cadillac                               |
| 235-91602 | Crankshaft Position Sensor FSK | 179,294   | 2,088   | 2006  | 2011 | Buick & Cadillac                       |
| 235-91604 | Camshaft Position Sensor FSK   | 167,514   | 1,632   | 2006  | 2011 | Buick & Cadillac                       |
| 235-91606 | Camshaft Position Sensor FSK   | 37,420    | 0       | 1992  | 1998 | Volvo                                  |
| 235-91613 | Camshaft Position Sensor FSK   | 23,593    | 2,436   | 1990  | 1994 | Ford                                   |
| 235-91617 | Crankshaft Position Sensor FSK | 32,978    | 1,015   | 2004  | 2006 | Cadillac                               |
| 235-91623 | Camshaft Position Sensor FSK   | 9,922     | 1,974   | 2008  | 2009 | Chevrolet & Saturn                     |
| 235-91624 | Camshaft Position Sensor FSK   | 74,428    | 3,986   | 2002  | 2008 | Jaguar & Lincoln                       |
| 235-91626 | Crankshaft Position Sensor FSK | 7,656     | 385     | 2005  | 2006 | Jeep                                   |
| 235-91627 | Crankshaft Position Sensor FSK | 1,078,446 | 18,180  | 2011  | 2017 | Ford                                   |
| 235-91634 | Crankshaft Position Sensor FSK | 5,931     | 0       | 1983  | 1995 | Porsche                                |
| 235-91637 | Camshaft Position Sensor FSK   | 29,678    | 686     | 2007  | 2009 | Buick, Chevrolet & Pontiac             |
| 235-91646 | Camshaft Position Sensor FSK   | 11,780    | 456     | 2006  | 2010 | Cadillac                               |

| Part #    | Description - EN               | US VIO    | MX VIO  | Start | End  | Make                                    |
|-----------|--------------------------------|-----------|---------|-------|------|-----------------------------------------|
| 235-91650 | Cam/Crank Position Sensor FSK  | 7,130     | 0       | 1982  | 1991 | BMW                                     |
| 235-91652 | Crankshaft Position Sensor FSK | 18,614    | 306     | 2003  | 2006 | Porsche                                 |
| 235-91655 | Crankshaft Position Sensor FSK | 61,457    | 224     | 1997  | 2002 | Porsche                                 |
| 235-91665 | Crankshaft Position Sensor FSK | 2,385     | 0       | 2004  | 2006 | Suzuki                                  |
| 235-91670 | Cam/Crank Position Sensor FSK  | 1,766     | 0       | 1985  | 1988 | BMW                                     |
| 235-91690 | Crankshaft Position Sensor FSK | 51,938    | 0       | 2009  | 2019 | Genesis, Hyundai & Kia                  |
| 235-91701 | Camshaft Position Sensor FSK   | 193,101   | 5,018   | 2012  | 2019 | Dodge, Fiat & Jeep                      |
| 235-91703 | Crankshaft Position Sensor FSK | 57,230    | 847     | 2003  | 2008 | Porsche                                 |
| 235-91708 | Crankshaft Position Sensor FSK | 135       | 0       | 1994  | 1995 | Saab                                    |
| 235-91714 | Crankshaft Position Sensor FSK | 437,409   | 38,515  | 2010  | 2019 | Ford                                    |
| 235-91726 | Crankshaft Position Sensor FSK | 978       | 0       | 1995  | 1996 | Land Rover                              |
| 235-91733 | Camshaft Position Sensor FSK   | 17,161    | 6       | 2007  | 2015 | Mercedes-Benz                           |
| 235-91734 | Camshaft Position Sensor FSK   | 43,972    | 827     | 2009  | 2018 | Porsche                                 |
| 235-91740 | Camshaft Position Sensor FSK   | 17,161    | 6       | 2007  | 2015 | Mercedes-Benz                           |
| 235-91742 | Crankshaft Position Sensor FSK | 22,117    | 279     | 1995  | 2005 | Porsche                                 |
| 235-91748 | Camshaft Position Sensor FSK   | 249,142   | 399     | 2008  | 2015 | Subaru                                  |
| 235-91749 | Crankshaft Position Sensor FSK | 7,663     | 231     | 2008  | 2010 | Porsche                                 |
| 235-91766 | Crankshaft Position Sensor FSK | 1,167     | 0       | 1984  | 1984 | Porsche                                 |
| 235-91779 | Crankshaft Position Sensor FSK | 503       | 773     | 1990  | 1993 | Volkswagen                              |
| 235-91780 | Camshaft Position Sensor FSK   | 281,940   | 540     | 2008  | 2020 | Subaru                                  |
| 235-91790 | Crankshaft Position Sensor FSK | 408,434   | 11,787  | 2012  | 2017 | Kia                                     |
| 235-91842 | Crankshaft Position Sensor FSK | 13,439    | 219     | 2004  | 2011 | Porsche                                 |
| 235-91852 | Crankshaft Position Sensor FSK | 14,071    | 376     | 2009  | 2012 | Porsche                                 |
| 235-91854 | Camshaft Position Sensor FSK   | 543       | 0       | 1992  | 1997 | Audi                                    |
| 235-91859 | Camshaft Position Sensor FSK   | 94,809    | 157     | 2010  | 2012 | Subaru                                  |
| 235-91860 | Camshaft Position Sensor FSK   | 146,889   | 206     | 2010  | 2017 | Subaru                                  |
| 235-91880 | Camshaft Position Sensor FSK   | 30,002    | 5,288   | 1999  | 2002 | Oldsmobile                              |
| 235-91909 | Crankshaft Position Sensor FSK | 90,002    | 0       | 2014  | 2019 | Jeep & Ram                              |
| 235-91998 | Crankshaft Position Sensor FSK | 0         | 59,404  | 1994  | 1994 | Nissan                                  |
| 235-92055 | Crankshaft Position Sensor FSK | 694       | 0       | 1994  | 1999 | Ferrari                                 |
| 235-92056 | Crankshaft Position Sensor FSK | 11        | 0       | 1996  | 1998 | Ferrari                                 |
| 235-92059 | Crankshaft Position Sensor FSK | 3,406     | 0       | 1990  | 1994 | Porsche                                 |
| 235-92060 | Crankshaft Position Sensor FSK | 345       | 0       | 1989  | 1989 | Porsche                                 |
| 235-92064 | Crankshaft Position Sensor FSK | 2,151     | 107     | 1997  | 1998 | Audi                                    |
| 235-92093 | Camshaft Position Sensor FSK   | 566,762   | 7,609   | 2012  | 2019 | Hyundai & Kia                           |
| 235-92101 | Crankshaft Position Sensor FSK | 394       | 0       | 1993  | 1995 | Jaguar                                  |
| 240-91043 | Vehicle Speed Sensor FSK       | 43,123    | 20,955  | 1995  | 2000 | Mercury & Nissan                        |
| 240-91058 | Vehicle Speed Sensor FSK       | 1,991,711 | 466,612 | 1992  | 2001 | Ford, Lincoln & Mercury                 |
| 240-91063 | Vehicle Speed Sensor FSK       | 2,340,481 | 154,147 | 2003  | 2012 | Chrysler, Dodge, Jeep, Mitsubishi & Ram |
| 240-91068 | Vehicle Speed Sensor FSK       | 1,616,078 | 254,079 | 1997  | 2011 | Ford & Mercury                          |
| 240-91073 | Vehicle Speed Sensor FSK       | 114,874   | 9,191   | 2004  | 2009 | Chevrolet & Pontiac                     |
| 240-91077 | Vehicle Speed Sensor FSK       | 45,850    | 82,165  | 1995  | 2002 | Ford & Mercury                          |
| 240-91078 | Vehicle Speed Sensor FSK       | 915,113   | 106,271 | 1999  | 2008 | Ford, Mazda & Mercury                   |
| 240-91090 | Vehicle Speed Sensor FSK       | 235,760   | 187,543 | 1995  | 2000 | Ford & Mercury                          |
| 240-91091 | Vehicle Speed Sensor FSK       | 211,577   | 107,134 | 1995  | 2002 | Ford, Lincoln & Mercury                 |
| 240-91103 | Vehicle Speed Sensor FSK       | 25,800    | 27,367  | 1995  | 1999 | Chrysler, Dodge, Eagle & Mitsubishi     |
| 240-91125 | Vehicle Speed Sensor FSK       | 2,705,095 | 285,999 | 1997  | 2005 | Ford & Lincoln                          |
| 240-91128 | Vehicle Speed Sensor FSK       | 2,216,594 | 230,407 | 1999  | 2014 | Ford                                    |
| 240-91133 | Vehicle Speed Sensor FSK       | 708,909   | 33,287  | 1999  | 2004 | Ford                                    |
| 240-91147 | Vehicle Speed Sensor FSK       | 3,022,587 | 51,610  | 2007  | 2019 | Chrysler, Dodge & Ram                   |
| 240-91159 | Vehicle Speed Sensor FSK       | 56,058    | 77,737  | 2009  | 2011 | Chevrolet & Pontiac                     |

**MAY 2021**

| Part #     | Description - EN            | US VIO    | MX VIO  | Start | End  | Make                                                         |
|------------|-----------------------------|-----------|---------|-------|------|--------------------------------------------------------------|
| 242-1204   | Knock Sensor                | 769,395   | 95,327  | 2002  | 2010 | Ford, Mazda & Mercury                                        |
| 242-91016  | Knock Sensor FSK            | 311,588   | 84,487  | 1987  | 1995 | Buick, Cadillac, Chevrolet, GMC, Oldsmobile & Pontiac        |
| 242-91017  | Knock Sensor FSK            | 124,621   | 98,612  | 1981  | 1995 | Buick, Cadillac, Chevrolet, Oldsmobile & Pontiac             |
| 242-91018  | Knock Sensor FSK            | 723,341   | 62,757  | 1981  | 2002 | Buick, Cadillac, Chevrolet, GMC, Isuzu, Oldsmobile & Pontiac |
| 242-91019  | Knock Sensor FSK            | 17,594    | 8,905   | 1995  | 1995 | Buick, Chevrolet, Oldsmobile & Pontiac                       |
| 242-91022  | Knock Sensor FSK            | 717,499   | 125,978 | 1996  | 2001 | Chevrolet, GMC, Isuzu & Oldsmobile                           |
| 242-91023  | Knock Sensor FSK            | 511,985   | 158,386 | 1990  | 1997 | Cadillac, Chevrolet, GMC & Pontiac                           |
| 242-91024  | Knock Sensor FSK            | 443,674   | 618,714 | 1987  | 2015 | Infiniti, Mercury & Nissan                                   |
| 242-91026  | Knock Sensor FSK            | 53,155    | 84,731  | 1999  | 2001 | Volkswagen                                                   |
| 242-91027  | Knock Sensor FSK            | 775,821   | 34,458  | 1995  | 2019 | BMW, Kia, Mini, Porsche & Saab                               |
| 242-91031  | Knock Sensor FSK            | 63,736    | 24,663  | 1992  | 1995 | Chevrolet & GMC                                              |
| 242-91032  | Knock Sensor FSK            | 78,264    | 36,190  | 1992  | 1996 | Chevrolet, GMC & Oldsmobile                                  |
| 242-91034  | Knock Sensor FSK            | 1,910,043 | 338,469 | 1985  | 2002 | Buick, Cadillac, Chevrolet, GMC, Oldsmobile & Pontiac        |
| 242-91039  | Knock Sensor FSK            | 5,329,695 | 208,628 | 1998  | 2007 | Buick, Cadillac, Chevrolet, GMC, Hummer, Isuzu & Pontiac     |
| 242-91047  | Knock Sensor FSK            | 1,076,217 | 88,799  | 2002  | 2013 | Chrysler, Dodge, Jeep, Mitsubishi & Ram                      |
| 242-91050  | Knock Sensor FSK            | 2,705,811 | 410,010 | 2003  | 2019 | Infiniti, Nissan & Smart                                     |
| 242-91051  | Knock Sensor FSK            | 640,369   | 74,209  | 2000  | 2005 | Cadillac, Chevrolet, GMC, Oldsmobile & Saturn                |
| 242-91055  | Knock Sensor FSK            | 8,644,875 | 563,542 | 2003  | 2019 | Chrysler, Dodge, Fiat, Jeep, Ram & SRT                       |
| 242-91061  | Knock Sensor FSK            | 967,080   | 61,068  | 1998  | 2010 | Chrysler & Dodge                                             |
| 242-91080  | Knock Sensor FSK            | 54,277    | 6,304   | 1996  | 2000 | Chevrolet & GMC                                              |
| 242-91100  | Knock Sensor FSK            | 7,636     |         | 2000  | 2002 | Hyundai                                                      |
| 242-91111  | Knock Sensor FSK            | 349,101   |         | 2003  | 2010 | Hyundai & Kia                                                |
| 243-1001   | Flex Fuel Sensor            | 1,884,599 | 76,892  | 2000  | 2005 | Chevrolet & GMC                                              |
| 243-1004   | Flex Fuel Sensor            | 445,094   | 4,852   | 2011  | 2018 | Buick, Chevrolet & GMC                                       |
| 250-24119  | O2 Sensor OE                | 0         | 31,193  | 2004  | 2014 | Chevrolet & Fiat                                             |
| 250-241256 | O2 Sensor OE                | 677,712   | 12,003  | 2017  | 2021 | Honda                                                        |
| 250-241266 | O2 Sensor OE                | 352,277   | 7,426   | 2020  | 2020 | Chevrolet & GMC                                              |
| 250-241268 | O2 Sensor OE                | 386,775   | 7,426   | 2020  | 2020 | Chevrolet & GMC                                              |
| 250-241269 | O2 Sensor OE                | 126,183   | 2,015   | 2019  | 2020 | Buick, Cadillac, Chevrolet & GMC                             |
| 250-25155  | O2 Sensor OE                | 9,412     | 0       | 2020  | 2020 | Buick                                                        |
| 255-1163   | Fuel Pressure Regulator     | 452,050   | 660,432 | 1993  | 2015 | Nissan                                                       |
| 350-341032 | O2 Sensor Aftermarket       | 126,305   | 1,643   | 2015  | 2020 | Volvo                                                        |
| 350-34351  | O2 Sensor Aftermarket       | 0         | 31,193  | 2004  | 2014 | Chevrolet & Fiat                                             |
| 550-1000   | Fuel Injector Throttle Body | 12,111    | 1,127   | 1995  | 1997 | Chevrolet & GMC                                              |
| 920-1090   | Ignition Coil               | 134,009   |         | 2005  | 2010 | Hyundai & Kia                                                |
| 920-1152   | Ignition Coil               | 3,171     |         | 1995  | 1995 | Land Rover                                                   |
| 921-2296   | Ignition Coil on Plug       | 816,306   | 1,747   | 2011  | 2020 | Mercedes-Benz                                                |

| Part #   | Description - EN                 | US VIO     | MX VIO    | Start | End  | Make                                                                                                                                                                                                                                                                                                                                                                                                |
|----------|----------------------------------|------------|-----------|-------|------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 924-1485 | Wire Set, TCP 12-CYL             | 2,077      | 269       | 1988  | 2001 | BMW                                                                                                                                                                                                                                                                                                                                                                                                 |
| 924-1550 | Wire Set, TCP 7mm 4-CYL Univ Mag | 3,700,316  | 1,949,706 | 1960  | 2013 | Alfa Romeo, American Motors, Asuna, Austin, Austin Healey, Buick, Cadillac, Checker, Chevrolet, Chrysler, Daewoo, Daihatsu, Dodge, Eagle, Fiat, Ford, Geo, GMC, Honda, Hyundai, International, Isuzu, Jeep, Kia, Lada, Lancia, Mazda, Mercury, Merkur, Mini, Mitsubishi, Nissan, Oldsmobile, Opel, Peugeot, Plymouth, Pontiac, Renault, Saab, Saturn, Subaru, Suzuki, Toyota, Triumph, Volvo & Yugo |
| 924-1551 | Wire Set, TCP 7mm 4-Cyl Univ Cu  | 144,547    | 272,476   | 1960  | 2005 | Audi, Porsche & Volkswagen                                                                                                                                                                                                                                                                                                                                                                          |
| 924-1552 | Wire Set, TCP 7mm 8-Cyl Univ Mag | 11,010,594 | 1,433,342 | 1957  | 2019 | American Motors, Austin Healey, Buick, Cadillac, Checker, Chevrolet, Chrysler, DeLorean, Dodge, Eagle, Ford, GMC, Hyundai, International, Isuzu, Jeep, Mazda, Mercury, Mitsubishi, Nissan, Oldsmobile, Peugeot, Plymouth, Pontiac, Saturn, Studebaker, Subaru, Toyota, Triumph, Volkswagen & Volvo                                                                                                  |
| 924-1553 | Wire Set, TCP 7mm 8-Cyl Univ Mag | 12,271,198 | 996,948   | 1958  | 2015 | American Motors, Buick, Cadillac, Chevrolet, Chrysler, DeTomaso, Dodge, Ford, GMC, Hummer, International, Jaguar, Jeep, Land Rover, Lincoln, Mazda, Mercury, Nissan, Oldsmobile, Plymouth, Pontiac, Ram, Saab, Studebaker, Sunbeam, Toyota & Triumph                                                                                                                                                |
| 924-1554 | Wire Set, TCP 7mm 8-Cyl Univ Mag | 2,817,771  | 408,032   | 1958  | 2003 | AM General, Buick, Cadillac, Checker, Chevrolet, Chrysler, Dodge, Ford, GMC, Mercury, Oldsmobile, Plymouth & Pontiac                                                                                                                                                                                                                                                                                |
| 924-1980 | Wire Set, TCP 7mm 4-Cyl          | 11,597     |           | 1997  | 1997 | Subaru                                                                                                                                                                                                                                                                                                                                                                                              |