

Manifold Absolute Pressure Sensor

26 NEW SKUs



Walker # 225-1299

2012-2020

Mazda, Scion & Toyota

US VIO: 1,927,883

MX VIO: 232,878

Oxygen Sensor - OEM

7 NEW SKUs



Walker # 250-54125

2018-2020

Lexus & Toyota

US VIO: 1,599,289

MX VIO: 22,362

Throttle Position Sensor

5 NEW SKUs



Walker # 200-1473

2001-2006

Acura & Honda

US VIO: 1,266,803

MX VIO: 89,582

Mass Air Flow Sensor Only

2 NEW SKUs



Walker # 245-1386

2016-2020

Acura & Honda

US VIO: 3,169,174

MX VIO: 99,912

Ignition Knock Sensor

3 NEW SKUs

Walker # 242-1091
2008-2013
Acura & Honda
US VIO: 1,646,847
MX VIO: 64,618



Throttle Position Sensor FSK®

3 NEW SKUs

Walker # 200-91110
1995-1998
Dodge
US VIO: 115,666
MX VIO: 11,300



O2 Sensor Aftermarket

2 NEW SKUs

Walker # 350-64112
2018-2020
Lexus & Toyota
US VIO: 1,599,289
MX VIO: 22,362



Idle Air Control Valve FSK®

1 NEW SKU

Walker # 215-92069
2004-2008
Ford, Mazda & Mercury
US VIO: 554,288
MX VIO: 43,598



Camshaft Position Sensor FSK®

1 NEW SKU

Walker # 235-91190
2008-2012
Chevrolet, GMC, Hummer, Isuzu & Saab
US VIO: 243,169
MX VIO: 21,471



Crankshaft Position Sensor

1 NEW SKU

Walker # 235-2358
2020-2021
Ford
US VIO: 113,206



Part #	Description - EN	US VIO	MX VIO	Start End	Make
200-1340	Throttle Position Sensor	16,983	349,477	1998 2004	Dodge
200-1369	Throttle Position Sensor		2,558	1983 1984	Ford
200-1415	Throttle Position Sensor	597	2,619	2002 2005	Land Rover
200-1473	Throttle Position Sensor	89,582	1,266,803	2001 2006	Acura & Honda
200-1500	Throttle Position Sensor		2,001	2005 2005	Saab
200-91110	Throttle Position Sensor FSK	11,300	115,666	1995 1998	Dodge
200-91225	Throttle Position Sensor FSK		88,613	1997 2005	Kia & Mazda
200-91351	Throttle Position Sensor FSK	3,149	19,403	2000 2004	Volvo
215-92069	Idle Air Control Valve FSK	43,598	554,288	2004 2008	Ford, Mazda & Mercury
225-1110	Manifold Absolute Pressure Sensor	4,578	656,605	2016 2021	Cadillac & Chevrolet
225-1174	Manifold Absolute Pressure Sensor	10,865	1,267,881	2017 2019	Buick, Chevrolet & MC
225-1183	Manifold Absolute Pressure Sensor	27	10,545	2000 2000	Volvo
225-1240	Manifold Absolute Pressure Sensor		195,647	2011 2016	Mini
225-1261	Manifold Absolute Pressure Sensor	2	27,616	2014 2020	BMW
225-1276	Manifold Absolute Pressure Sensor	87	34,251	2009 2013	BMW
225-1279	Manifold Absolute Pressure Sensor	7,502	91,602	2008 2011	Mitsubishi
225-1296	Manifold Absolute Pressure Sensor	1,472	72,712	2007 2012	Acura
225-1299	Manifold Absolute Pressure Sensor	232,878	1,927,883	2012 2020	Mazda, Scion & Toyota
225-1302	Manifold Absolute Pressure Sensor	5,997	1,003,876	2011 2020	Mercedes-Benz
225-1326	Manifold Absolute Pressure Sensor	17,690	177,563	2014 2020	BMW & Mini
225-1327	Manifold Absolute Pressure Sensor	42	5,601	2014 2020	BMW
225-1330	Manifold Absolute Pressure Sensor	9,095	840,618	2015 2020	Ford & Lincoln
225-1336	Manifold Absolute Pressure Sensor	23,276	489,745	2009 2018	Audi & Volkswagen
225-1342	Manifold Absolute Pressure Sensor		3,365	2014 2017	Ram
225-1343	Manifold Absolute Pressure Sensor	21,287	634,504	2016 2020	BMW
225-1344	Manifold Absolute Pressure Sensor	18,153	402,702	2015 2020	Audi & Volkswagen
225-1357	Manifold Absolute Pressure Sensor		71,450	1997 2000	Toyota

Part #	Description - EN	US VIO	MX VIO	Start End	Make
225-1363	Manifold Absolute Pressure Sensor	1,049	6,689	2015 2017	Dodge
225-1372	Manifold Absolute Pressure Sensor	18,066	336,598	2017 2020	Dodge, Jeep & Ram
225-1385	Manifold Absolute Pressure Sensor	278	5,515	2016 2017	Smart
225-1393	Manifold Absolute Pressure Sensor	2,975	22,148	2018 2021	Dodge, Jeep & RAM
225-1394	Manifold Absolute Pressure Sensor		84,386	2019 2020	Jeep
225-1414	Manifold Absolute Pressure Sensor	111	2,914	2017 2019	Alfa Romeo
225-1415	Manifold Absolute Pressure Sensor		10,638	2017 2020	Fiat
225-1421	Manifold Absolute Pressure Sensor			2018 2018	Mercedes-Benz
235-2358	Crankshaft Position Sensor		113,206	2020 2021	Ford
235-91190	Camshaft Position Sensor FSK	21,471	243,169	2008 2012	Chevrolet, GMC, Hummer, Isuzu & Saab
242-1091	Ignition Knock Sensor	64,618	1,646,847	2008 2013	Acura & Honda
242-1096	Ignition Knock Sensor	14,393		2007 2016	Mini
242-1112	Ignition Knock Sensor		155,302	2006 2014	Hyundai & Kia
245-1386	Mass Air Flow, Sensor Only	99,912	3,169,174	2016 2020	Acura, Honda
245-1655	Mass Air Flow, Sensor Only	2,015	123,702	2019 2021	Buick, Cadillac, Chevrolet & GMC
250-241272	Oxygen Sensor OEM	4,463	46,356	2018 2020	BMW
250-241274	Oxygen Sensor OEM	4		2019 2020	Land Rover
250-241275	Oxygen Sensor OEM	327	14,689	2020 2020	Land Rover
250-241276	Oxygen Sensor OEM	7,858	282,779	2015 2021	Genesis, Hyundai & Kia
250-24977	Oxygen Sensor OEM	21,844	177,997	2017 2018	Kia
250-54125	Oxygen Sensor OEM	22,362	1,599,289	2018 2020	Lexus & Toyota
250-54127	Oxygen Sensor OEM	1,447	138,534	2019 2019	Nissan
350-34856	Oxygen Sensor - Aftermarket	21,844	177,997	2017 2018	Kia
350-64112	Oxygen Sensor - Aftermarket	22,362	1,599,289	2018 2020	Lexus & Toyota