

292 NEW FULL SERVICE KIT® SKUs



Walker Product's Full Service Kits® are a totally new concept in selling an engine management sensor solution. This product offering is exclusive to the automotive aftermarket, and has received the MOTOR Top 20 Tools+ Award for it's innovative features that help technicians repair vehicles correctly - the first time. Our Full Service Kits® contain not only the base sensor, but also provide the technician or DIY'er the mating connector and pigtail. We even include the butt splices and heat shrink to ensure a watertight connection.

Camshaft & Crankshaft Position Sensor FSK®

204 NEW SKUs



Walker # 235-91002

1990-2019

Ford, Jaguar, Lincoln

& Mercury

US VIO: 6,892,712

MX VIO: 580,739

Idle Air Control Valve FSK®

26 NEW SKUs



Walker # 215-92061

2001-2008

Ford, Mazda & Mercury

US VIO: 640,180

MX VIO: 56,052

Knock Sensor FSK®

21 NEW SKUs



Walker # 242-91055

2003-2019

Chrysler, Dodge, Fiat, Jeep, Ram & SRT

US VIO: 8,644,875

MX VIO: 563,542

Throttle Position Sensor FSK®

16 NEW SKUs



Walker # 200-91240

1997-2004

Lexus & Toyota

US VIO: 1,612,725

MX VIO: 47,711

Vehicle Speed Sensor FSK®

15 NEW SKUs



Walker # 240-91147

2007-2019

Chrysler, Dodge & Ram

US VIO: 3,022,587

MX VIO: 51,610

Air Charge Temp Sensor FSK®

10 NEW SKUs



Walker # 210-91035

1991-2005

Buick, Cadillac, Chevrolet, Oldsmobile

& Pontiac

US VIO: 1,283,854

MX VIO: 191,716

Throttle Position Sensor

10 NEW SKUs

Walker # 200-1425
2013-2019
Nissan
US VIO: 2,927,552
MX VIO: 12,426



Wire Set

7 NEW SKUs

Walker # 924-1552
1957-2019
US VIO: 11,010,594
MX VIO: 1,433,342

American Motors, Austin Healey, Buick, Cadillac, Checker, Chevrolet, Chrysler, DeLorean, Dodge, Eagle, Ford, GMC, Hyundai, International, Isuzu, Jeep, Mazda, Mercury, Mitsubishi, Nissan, Oldsmobile, Peugeot, Plymouth, Pontiac, Saturn, Studebaker, Subaru, Toyota, Triumph, Volkswagen & Volvo



O2 Sensor OE

6 NEW SKUs

Walker # 250-241256
2017-2021
Honda
US VIO: 677,712
MX VIO: 12,003



MAP Sensor

5 NEW SKUs


Walker # 225-1278
2006-2012
Subaru
US VIO: 946,400
MX VIO: 1,308



Ignition Coil

3 NEW SKUs

Walker # 920-1090
2005-2010
Hyundai & Kia
US VIO: 134,009



O2 Sensor Aftermarket

2 NEW SKUs


Walker # 350-341032
2015-2020
Volvo
US VIO: 126,305
MX VIO: 1,643



Flex Fuel Sensor

2 NEW SKUs

Walker # 243-1001
2000-2005
Chevrolet & GMC
US VIO: 1,884,599
MX VIO: 76,892



Knock Sensor

1 NEW SKU

Walker # 242-1204
2002-2010
Ford, Mazda & Mercury
US VIO: 769,395
MX VIO: 95,327



Fuel Pressure Regulator

1 NEW SKU


Walker # 255-1163
1993-2015
Nissan
US VIO: 452,050
MX VIO: 660,432



Fuel Injector Throttle Body

1 NEW SKU

Walker # 550-1000
1995-1997
Chevrolet & GMC
US VIO: 12,111
MX VIO: 1,127



Camshaft Position Sensor

1 NEW SKU

Walker # 235-2278
2013-2017
Jaguar
US VIO: 12,045
MX VIO: 209



MAY 2021

Part #	Description - EN	US VIO	MX VIO	Start	End	Make
200-1328	Throttle Position Sensor	7,237	11,242	1992	1994	Ford & Mercury
200-1344	Throttle Position Sensor		6,814	2004	2005	Fiat
200-1371	Throttle Position Sensor	3,754		1989	1995	Porsche
200-1374	Throttle Position Sensor	54,132	1,319	2000	2004	Honda & Isuzu
200-1379	Throttle Position Sensor	4,398		1987	1992	Jaguar
200-1394	Throttle Position Sensor	31,093		2006	2008	Mazda
200-1425	Throttle Position Sensor	2,927,552	12,426	2013	2019	Nissan
200-1444	Throttle Position Sensor	126,572	7,320	2004	2004	Ford
200-1457	Throttle Position Sensor	683		1990	1992	Volkswagen
200-1480	Throttle Position Sensor		35,622	2012	2014	Dodge
200-91001	Throttle Position Sensor FSK	24,196	234	1982	1991	Cadillac, Dodge, Eagle, Jeep & Renault
200-91060	Throttle Position Sensor FSK	320,784	65,484	1994	2003	Ford, Mazda & Mercury
200-91090	Throttle Position Sensor FSK	115,170	29,712	1996	1998	Ford & Mercury
200-91096	Throttle Position Sensor FSK	778,105	63,310	1997	2002	Dodge & Jeep
200-91099	Throttle Position Sensor FSK	449,224	64,301	1998	2010	Chrysler & Dodge
200-91101	Throttle Position Sensor FSK	141,134	81,297	1998	2005	Chrysler, Dodge & Plymouth
200-91104	Throttle Position Sensor FSK	91,445	19,463	1998	2004	Chrysler, Dodge & Plymouth
200-91105	Throttle Position Sensor FSK	1,281,096	102,688	1998	2007	Chrysler, Dodge & Plymouth
200-91237	Throttle Position Sensor FSK	1,479,552	52,024	1997	2006	Chevrolet, Pontiac, Scion & Toyota
200-91240	Throttle Position Sensor FSK	1,612,725	47,711	1997	2004	Lexus & Toyota
200-91326	Throttle Position Sensor FSK	53,117	44,618	1991	1997	Saturn
200-91337	Throttle Position Sensor FSK	100,935	14,209	2000	2002	Saturn
200-91423	Throttle Position Sensor FSK	64,396	10,186	2002	2007	Mitsubishi
200-91440	Throttle Position Sensor FSK	47,845	17,286	2003	2003	Ford
200-91448	Throttle Position Sensor FSK	1,986	3,177	1980	1982	Buick, Cadillac, Chevrolet, Oldsmobile & Pontiac
200-91453	Throttle Position Sensor FSK	22,873	438	1994	1995	Chevrolet
210-91007	Air Charge Temp Sensor FSK	51,992	28,153	1986	1996	Chrysler, Dodge & Plymouth
210-91023	Air Charge Temp Sensor FSK		58,235	1993	2003	Volkswagen
210-91028	Air Charge Temp Sensor FSK		19,625	1996	1997	Chevrolet
210-91029	Air Charge Temp Sensor FSK	35,087	35,717	1995	2002	Volkswagen
210-91035	Air Charge Temp Sensor FSK	1,283,854	191,716	1991	2005	Buick, Cadillac, Chevrolet, Oldsmobile & Pontiac
210-91038	Air Charge Temp Sensor FSK	384,581		1995	2010	Hyundai & Kia
210-91051	Air Charge Temp Sensor FSK	230,911	27,545	1997	2006	Audi & Volkswagen
210-91052	Air Charge Temp Sensor FSK	625,655	19,411	1995	2006	BMW & Land Rover
210-91056	Air Charge Temp Sensor FSK	113,661	9,191	1999	2008	Chevrolet & Daewoo
210-91057	Air Charge Temp Sensor FSK	4,399	54	1996	1997	Porsche
215-91021	Idle Air Control Valve FSK	90,948	16,562	1995	2002	Acura, Chevrolet, GMC, Honda, Isuzu & Oldsmobile
215-91061	Idle Air Control Valve FSK	95,807	176,026	1993	2002	Volkswagen
215-91062	Idle Air Control Valve FSK	260	46	1992	1994	Volkswagen
215-91074	Idle Air Control Valve FSK	314,632	49,706	1991	1997	Jeep
215-91075	Idle Air Control Valve FSK	191,576	60,031	1995	2002	Saturn
215-91077	Idle Air Control Valve FSK			1998	2009	Volkswagen
215-91078	Idle Air Control Valve FSK	413,690	82,548	2002	2005	Chevrolet, Oldsmobile, Pontiac & Saturn
215-91079	Idle Air Control Valve FSK	147	42	1995	1996	Chevrolet & GMC
215-92012	Idle Air Control Valve FSK	31,455	13,538	1991	1993	Ford
215-92016	Idle Air Control Valve FSK	12,995	1,070	1995	1996	Ford
215-92020	Idle Air Control Valve FSK	11,463	12,124	1992	1995	Ford & Mercury

Part #	Description - EN	US VIO	MX VIO	Start	End	Make
215-92025	Idle Air Control Valve FSK	106,019	71,775	1996	1999	Ford, Mercury
215-92041	Idle Air Control Valve FSK	55,927	71,508	1997	1999	Ford & Mercury
215-92061	Idle Air Control Valve FSK	640,180	56,052	2001	2008	Ford, Mazda & Mercury
215-92062	Idle Air Control Valve FSK	223,790	122,811	1999	2004	Ford & Mercury
215-92063	Idle Air Control Valve FSK	310,512	43,393	2000	2006	Ford, Mazda & Mercury
215-92068	Idle Air Control Valve FSK	355,793	46,165	2002	2007	Ford & Mercury
215-92070	Idle Air Control Valve FSK	227,904	25,233	2002	2004	Ford
215-92075	Idle Air Control Valve FSK	199	289	1995	1995	Ford
215-92079	Idle Air Control Valve FSK	54,187	4,817	2000	2003	Ford & Lincoln
215-92080	Idle Air Control Valve FSK	128,332	9,904	2002	2004	Ford
215-92083	Idle Air Control Valve FSK	59,843	4,867	2003	2004	Ford
215-92086	Idle Air Control Valve FSK	52,688	11,319	2000	2000	Ford & Mercury
215-92088	Idle Air Control Valve FSK	53,810	41,690	1999	2001	Ford
215-92105	Idle Air Control Valve FSK	106,373	73,461	2002	2009	Ford
215-92107	Idle Air Control Valve FSK	1,691	6,719	1995	1995	Ford & Mercury
225-1117	MAP Sensor	25	6	2000	2000	Ford
225-1190	MAP Sensor	18,916	3,360	2004	2004	Mitsubishi
225-1218	MAP Sensor	52,298	382	2008	2015	Smart
225-1278	MAP Sensor	946,400	1,308	2006	2012	Subaru
225-1318	MAP Sensor	74,791	225	2014	2019	Cadillac
235-2278	Camshaft Position Sensor	12,045	209	2013	2017	Jaguar
235-91002	Camshaft Position Sensor FSK	6,892,712	580,739	1990	2019	Ford, Jaguar, Lincoln & Mercury
235-91012	Crankshaft Position Sensor FSK	1,846	0	1985	1988	Buick, Oldsmobile & Pontiac
235-91016	Crankshaft Position Sensor FSK	55,612	55,906	1980	1991	Ford, Lincoln & Mercury
235-91018	Crankshaft Position Sensor FSK	274,207	227,763	1991	2004	Ford & Mercury
235-91020	Crankshaft Position Sensor FSK	114,472	51,406	1993	1999	Cadillac, Oldsmobile & Shelby
235-91033	Crankshaft Position Sensor FSK	17,753	1,218	2001	2006	Mitsubishi
235-91034	Crankshaft Position Sensor FSK	69,687	85,026	2008	2011	Chevrolet, Pontiac & Saturn
235-91039	Camshaft Position Sensor FSK	550	233	1997	1997	Cadillac
235-91041	Camshaft Position Sensor FSK	422,291	31,556	2011	2019	Ford
235-91042	Camshaft Position Sensor FSK	72,176	9,262	1998	2005	Cadillac & Saturn
235-91044	Crankshaft Position Sensor FSK	69,429	1,461	2003	2011	Cadillac, Chevrolet, Saab & Saturn
235-91045	Crankshaft Position Sensor FSK	20,597	2,007	2002	2003	Chevrolet & Saturn
235-91049	Crankshaft Position Sensor FSK	4,033	126	1992	1998	Audi
235-91051	Camshaft Position Sensor FSK	71,146	188,925	1999	2014	Dodge, Hyundai & Kia
235-91057	Crankshaft Position Sensor FSK	5,439,755	252,040	1997	2009	Avanti, Buick, Cadillac, Chevrolet, GMC, Hummer, Isuzu, Pontiac & Saab
235-91065	Camshaft Position Sensor FSK	274,207	240,911	1991	2007	Ford & Mercury
235-91067	Camshaft Position Sensor FSK	984,418	342,303	1997	2012	Ford
235-91070	Camshaft Position Sensor FSK	1,350,164	274,424	1995	2008	Ford, Mazda & Mercury
235-91079	Crankshaft Position Sensor FSK	0	353,074	1994	2004	Chevrolet
235-91099	Camshaft Position Sensor FSK	17,154	1,483	2002	2006	Jeep
235-91105	Camshaft Position Sensor FSK	196,173	7,289	2006	2007	Buick, Chevrolet, GMC, Hummer, Isuzu & Saab
235-91107	Camshaft Position Sensor FSK	266,002	9,509	2004	2006	Chrysler & Dodge
235-91119	Crankshaft Position Sensor FSK	607,737	45,789	2004	2007	Buick, Chevrolet, Pontiac & Saturn
235-91122	Camshaft Position Sensor FSK	40,869	17,462	1998	2003	Chevrolet & Suzuki

MAY 2021

Part #	Description - EN	US VIO	MX VIO	Start	End	Make
235-91123	Camshaft Position Sensor FSK	1,303,731	135,945	1998	2007	Chrysler, Dodge, Jeep & Plymouth
235-91124	Camshaft Position Sensor FSK	122,213	40,750	1997	2014	Chrysler, Dodge, Eagle & Mitsubishi
235-91129	Cam/Crank Position Sensor FSK	8,888	10,097	1995	1998	Mercury
235-91130	Crankshaft Position Sensor FSK	573,264	145,894	1993	2008	Ford, Mazda & Mercury
235-91132	Crankshaft Position Sensor FSK	25,154	3,709	2000	2005	Saturn
235-91133	Crankshaft Position Sensor FSK	223,841	17,702	2000	2005	Cadillac, Oldsmobile, Pontiac & Shelby
235-91142	Crankshaft Position Sensor FSK	160,094	68,924	1995	2000	Infiniti & Nissan
235-91149	Camshaft Position Sensor FSK	103,210	2,659	2000	2004	Infiniti, Nissan
235-91150	Cam/Crank Position Sensor FSK	1,995,119	56,052	2002	2020	Infiniti & Nissan
235-91153	Crankshaft Position Sensor FSK	1,555,590	44,367	2006	2011	Buick, Chevrolet, Pontiac & Saturn
235-91158	Camshaft Position Sensor FSK	1,037,994	37,609	2006	2009	Buick, Chevrolet, Pontiac & Saturn
235-91166	Crankshaft Position Sensor FSK	8,988	0	1993	1999	Dodge & Mitsubishi
235-91180	Camshaft Position Sensor FSK	154,452	5,407	2004	2006	Buick & Cadillac
235-91181	Crankshaft Position Sensor FSK	70,248	3,588	2000	2006	Dodge & Hyundai
235-91183	Crankshaft Position Sensor FSK	49,031	14,658	1999	2005	Chrysler, Dodge & Mitsubishi
235-91184	Camshaft Position Sensor FSK	223,841	17,702	2000	2005	Cadillac, Oldsmobile & Pontiac
235-91185	Crankshaft Position Sensor FSK	166,011	6,270	1995	2001	Infiniti & Nissan
235-91191	Camshaft Position Sensor FSK	70,248	6,940	2000	2009	Dodge & Hyundai
235-91194	Cam/Crank Position Sensor FSK	206,742	6,080	2004	2009	Buick, Cadillac & Saab
235-91196	Camshaft Position Sensor FSK	219,897	44,526	2004	2017	Mitsubishi
235-91199	Camshaft Position Sensor FSK	36,902	3,088	2004	2008	Chevrolet & Suzuki
235-91202	Crankshaft Position Sensor FSK	1,736	12,697	1994	1998	Eagle & Mitsubishi
235-91206	Camshaft Position Sensor FSK	582,216	18,307	1999	2006	BMW
235-91211	Camshaft Position Sensor FSK	4,018,119	80,438	2006	2017	Buick, Chevrolet, GMC, Pontiac, Saab & Saturn
235-91215	Crankshaft Position Sensor FSK	1,848	0	1997	1999	Hyundai
235-91216	Crankshaft Position Sensor FSK	16,508	0	1995	2001	Hyundai
235-91218	Crankshaft Position Sensor FSK	20,502	0	1995	2002	Kia
235-91219	Crankshaft Position Sensor FSK	574,318	69,061	1996	2007	Ford & Mercury
235-91222	Camshaft Position Sensor FSK	319,953	72,083	1996	2006	Audi, Seat & Volkswagen
235-91228	Crankshaft Position Sensor FSK	68,036	21,004	2001	2005	Chrysler, Dodge & Mitsubishi
235-91230	Crankshaft Position Sensor FSK	86,405	0	2003	2006	Kia
235-91233	Camshaft Position Sensor FSK	67,474	0	1999	2005	Mazda
235-91234	Camshaft Position Sensor FSK	5,214,157	117,745	2004	2019	Buick, Cadillac, Chevrolet, GMC, Hummer, Isuzu, Pontiac & Saab
235-91241	Crankshaft Position Sensor FSK	664,244	132,933	1996	2008	Ford, Jaguar, Lincoln & Mercury
235-91256	Camshaft Position Sensor FSK	394,179	0	1999	2010	Hyundai & Kia
235-91257	Crankshaft Position Sensor FSK	52,107	0	1999	2006	Hyundai & Kia
235-91265	Crankshaft Position Sensor FSK	87,894	0	2001	2005	Hyundai & Kia
235-91277	Crankshaft Position Sensor FSK	965,955	26,922	2005	2019	Nissan & Suzuki
235-91281	Camshaft Position Sensor FSK	870,539	1,265	2006	2016	Hyundai & Kia
235-91293	Camshaft Position Sensor FSK	290,848	52,347	1994	2001	Ford & Mazda
235-91296	Camshaft Position Sensor FSK	448,803	29,416	2003	2009	Ford, Lincoln, Mazda & Mercury
235-91303	Crankshaft Position Sensor FSK	19,403	4,174	2000	2004	Volvo
235-91307	Crankshaft Position Sensor FSK	9,517	0	1987	2001	Kia & Volvo
235-91308	Camshaft Position Sensor FSK	52,319	1,039	1994	2000	Mercedes-Benz
235-91310	Crankshaft Position Sensor FSK	111,167	413,210	2004	2018	Chevrolet & Pontiac

Part #	Description - EN	US VIO	MX VIO	Start	End	Make
235-91313	Camshaft Position Sensor FSK	102,194	1,627	2005	2006	Jeep
235-91316	Crankshaft Position Sensor FSK	12,984	0	2003	2003	Mitsubishi
235-91320	Camshaft Position Sensor FSK	448,803	29,416	2003	2009	Ford, Lincoln, Mazda & Mercury
235-91321	Crankshaft Position Sensor FSK	68,266	1,605	1995	2013	BMW
235-91322	Crankshaft Position Sensor FSK	1,004,414	2,978	2005	2015	Dodge, Freightliner, Jeep & Mercedes-Benz
235-91324	Camshaft Position Sensor FSK	84,945	2,659	1998	2004	Acura, Honda & Isuzu
235-91326	Crankshaft Position Sensor FSK	51,993	9,553	1996	1997	Buick, Cadillac, Chevrolet & Pontiac
235-91334	Camshaft Position Sensor FSK	87,614	18,310	1991	2006	Ford, Lincoln & Mercury
235-91335	Camshaft Position Sensor FSK	822,541	9,211	2008	2011	Chrysler, Dodge & Jeep
235-91336	Camshaft Position Sensor FSK	7,941	0	1992	1995	BMW
235-91340	Camshaft Position Sensor FSK	64,396	10,186	2002	2007	Mitsubishi
235-91345	Crankshaft Position Sensor FSK	176,309	61,457	1996	2001	Ford, Laforza & Mercury
235-91349	Crankshaft Position Sensor FSK	950	0	1999	2002	Daewoo
235-91353	Crankshaft Position Sensor FSK	905,884	1,265	2006	2019	Genesis, Hyundai & Kia
235-91356	Crankshaft Position Sensor FSK	67,845	1,977	2001	2003	Infiniti & Nissan
235-91369	Camshaft Position Sensor FSK	5,851,597	98,247	2007	2019	Ford, Lincoln, Mazda & Mercury
235-91372	Crankshaft Position Sensor FSK	5,301,293	97,716	2007	2019	Ford, Lincoln, Mazda & Mercury
235-91376	Camshaft Position Sensor FSK	1,367,675	9,615	2000	2019	Chrysler, Dodge, Freightliner & Mercedes-Benz
235-91381	Camshaft Position Sensor FSK	827,915	1,222	2004	2015	Saab & Subaru
235-91382	Camshaft Position Sensor FSK	227,503	22,357	2006	2011	Dodge, Hyundai & Kia
235-91383	Camshaft Position Sensor FSK	60,595	4,857	1999	2014	Mazda
235-91385	Crankshaft Position Sensor FSK	63,535	0	2003	2006	Hyundai & Kia
235-91389	Crankshaft Position Sensor FSK	19,767	2,522	1997	2005	Mitsubishi
235-91390	Crankshaft Position Sensor FSK	24,474	0	1985	1995	Volvo
235-91406	Crankshaft Position Sensor FSK	19,608	118	1991	1995	BMW
235-91409	Crankshaft Position Sensor FSK	10,476	12,038	1994	1999	Chrysler, Eagle & Mitsubishi
235-91410	Camshaft Position Sensor FSK	16,160	0	1996	2001	Hyundai
235-91411	Crankshaft Position Sensor FSK	40,769	8,594	1991	2002	Lincoln
235-91419	Crankshaft Position Sensor FSK	638	0	1997	1999	Mitsubishi
235-91422	Crankshaft Position Sensor FSK	11,601	0	1997	2001	Mitsubishi
235-91423	Crankshaft Position Sensor FSK	27,365	41,001	1994	2002	Infiniti & Nissan
235-91424	Camshaft Position Sensor FSK	950	0	1999	2002	Daewoo
235-91428	Camshaft Position Sensor FSK	85,998	655	2001	2009	Subaru
235-91429	Crankshaft Position Sensor FSK	129,257	704	2006	2010	Hyundai & Kia
235-91431	Camshaft Position Sensor FSK	116,244	548	2002	2008	Mini
235-91433	Crankshaft Position Sensor FSK	212,557	24,572	2008	2020	Mitsubishi
235-91436	Camshaft Position Sensor FSK	17,523	0	2002	2004	Kia
235-91440	Crankshaft Position Sensor FSK	459	0	1993	1996	Eagle & Mitsubishi
235-91445	Crankshaft Position Sensor FSK	19,648	0	1987	1993	BMW
235-91447	Crankshaft Position Sensor FSK	10,453	690	2003	2006	Mitsubishi
235-91448	Camshaft Position Sensor FSK	715,261	5,396	1996	2019	Chrysler, Dodge, Freightliner, Jeep, Mercedes-Benz & Porsche
235-91450	Crankshaft Position Sensor FSK	6,144	0	1988	1995	BMW
235-91451	Crankshaft Position Sensor FSK	10,554	4	1998	2000	Chevrolet & GMC
235-91462	Camshaft Position Sensor FSK	129,257	704	2006	2010	Hyundai & Kia
235-91463	Camshaft Position Sensor FSK	129,257	704	2006	2010	Hyundai & Kia
235-91465	Crankshaft Position Sensor FSK	5,254	11,068	1996	2000	Volkswagen
235-91467	Camshaft Position Sensor FSK	2,228	0	1995	1999	Hyundai
235-91468	Camshaft Position Sensor FSK	1,094,386	18,906	2011	2019	Ford
235-91470	Crankshaft Position Sensor FSK	3,526	0	1993	1995	BMW

Part #	Description - EN	US VIO	MX VIO	Start	End	Make
235-91472	Crankshaft Position Sensor FSK	15,099	284	2003	2005	Land Rover
235-91473	Cam/Crank Position Sensor FSK	863	0	1988	1993	BMW
235-91475	Crankshaft Position Sensor FSK	13,268	389	2000	2003	BMW
235-91480	Camshaft Position Sensor FSK	4,033	126	1992	1998	Audi
235-91487	Camshaft Position Sensor FSK	803	0	1995	1995	BMW
235-91489	Camshaft Position Sensor FSK	3,488	4,345	1994	1997	Chevrolet, Oldsmobile & Pontiac
235-91490	Camshaft Position Sensor FSK	1,773,779	31,556	2013	2019	Ford
235-91495	Crankshaft Position Sensor FSK	823	0	1994	1996	Mitsubishi
235-91499	Camshaft Position Sensor FSK	2,683	0	2005	2007	Land Rover
235-91502	Camshaft Position Sensor FSK	48,613	0	2009	2019	Hyundai & Kia
235-91503	Camshaft Position Sensor FSK	3,543	0	1991	1992	BMW
235-91504	Crankshaft Position Sensor FSK	1,167	0	1992	1993	BMW
235-91506	Cam/Crank Position Sensor FSK	20	0	1990	1998	Audi
235-91514	Camshaft Position Sensor FSK	126,508	2,235	2005	2019	Porsche
235-91516	Crankshaft Position Sensor FSK	1,733	0	1984	1997	Audi
235-91520	Crankshaft Position Sensor FSK	373	0	1991	1995	Hyundai
235-91536	Cam/Crank Position Sensor FSK	775	0	1984	1988	Audi
235-91539	Crankshaft Position Sensor FSK	1,218	0	1990	1992	Alfa Romeo
235-91551	Crankshaft Position Sensor FSK	1,297	299	1992	1995	Volkswagen
235-91552	Camshaft Position Sensor FSK	1,058,510	2,986	2011	2019	Ford
235-91554	Camshaft Position Sensor FSK	165,120	477	2008	2017	Subaru
235-91559	Crankshaft Position Sensor FSK	42,091	189,779	1993	1999	Infiniti & Nissan
235-91564	Crankshaft Position Sensor FSK	2,012	1,026	1996	1998	Mitsubishi
235-91565	Crankshaft Position Sensor FSK	17,523	0	2002	2004	Kia
235-91567	Crankshaft Position Sensor FSK	26,604	17,906	1994	1996	Buick, Chevrolet, Oldsmobile & Pontiac
235-91569	Camshaft Position Sensor FSK	195,111	36,526	2006	2013	Mazda
235-91572	Camshaft Position Sensor FSK	30,766	5,748	2000	2003	Lincoln
235-91578	Camshaft Position Sensor FSK	94,791	10,720	2008	2011	Mitsubishi
235-91579	Cam/Crank Position Sensor FSK	22,582	9,590	2007	2011	Mitsubishi
235-91580	Crankshaft Position Sensor FSK	3	0	1996	1996	Mitsubishi
235-91581	Camshaft Position Sensor FSK	102,783	651	2002	2019	Jeep, Ram
235-91588	Crankshaft Position Sensor FSK	28	0	1996	1998	Hyundai
235-91591	Camshaft Position Sensor FSK	3,759	655	1998	2000	Chevrolet
235-91594	Crankshaft Position Sensor FSK	36,744	379	2009	2013	Chevrolet
235-91595	Crankshaft Position Sensor FSK	0	338,985	2002	2012	Chevrolet
235-91597	Crankshaft Position Sensor FSK	260,322	8,658	1999	2010	Ford, Jaguar, Land Rover & Lincoln
235-91599	Crankshaft Position Sensor FSK	21,758	39,959	1994	2002	Infiniti & Nissan
235-91600	Camshaft Position Sensor FSK	32,978	1,015	2004	2006	Cadillac
235-91602	Crankshaft Position Sensor FSK	179,294	2,088	2006	2011	Buick & Cadillac
235-91604	Camshaft Position Sensor FSK	167,514	1,632	2006	2011	Buick & Cadillac
235-91606	Camshaft Position Sensor FSK	37,420	0	1992	1998	Volvo
235-91613	Camshaft Position Sensor FSK	23,593	2,436	1990	1994	Ford
235-91617	Crankshaft Position Sensor FSK	32,978	1,015	2004	2006	Cadillac
235-91623	Camshaft Position Sensor FSK	9,922	1,974	2008	2009	Chevrolet & Saturn
235-91624	Camshaft Position Sensor FSK	74,428	3,986	2002	2008	Jaguar & Lincoln
235-91626	Crankshaft Position Sensor FSK	7,656	385	2005	2006	Jeep
235-91627	Crankshaft Position Sensor FSK	1,078,446	18,180	2011	2017	Ford
235-91634	Crankshaft Position Sensor FSK	5,931	0	1983	1995	Porsche
235-91637	Camshaft Position Sensor FSK	29,678	686	2007	2009	Buick, Chevrolet & Pontiac
235-91646	Camshaft Position Sensor FSK	11,780	456	2006	2010	Cadillac

Part #	Description - EN	US VIO	MX VIO	Start	End	Make
235-91650	Cam/Crank Position Sensor FSK	7,130	0	1982	1991	BMW
235-91652	Crankshaft Position Sensor FSK	18,614	306	2003	2006	Porsche
235-91655	Crankshaft Position Sensor FSK	61,457	224	1997	2002	Porsche
235-91665	Crankshaft Position Sensor FSK	2,385	0	2004	2006	Suzuki
235-91670	Cam/Crank Position Sensor FSK	1,766	0	1985	1988	BMW
235-91690	Crankshaft Position Sensor FSK	51,938	0	2009	2019	Genesis, Hyundai & Kia
235-91701	Camshaft Position Sensor FSK	193,101	5,018	2012	2019	Dodge, Fiat & Jeep
235-91703	Crankshaft Position Sensor FSK	57,230	847	2003	2008	Porsche
235-91708	Crankshaft Position Sensor FSK	135	0	1994	1995	Saab
235-91714	Crankshaft Position Sensor FSK	437,409	38,515	2010	2019	Ford
235-91726	Crankshaft Position Sensor FSK	978	0	1995	1996	Land Rover
235-91733	Camshaft Position Sensor FSK	17,161	6	2007	2015	Mercedes-Benz
235-91734	Camshaft Position Sensor FSK	43,972	827	2009	2018	Porsche
235-91740	Camshaft Position Sensor FSK	17,161	6	2007	2015	Mercedes-Benz
235-91742	Crankshaft Position Sensor FSK	22,117	279	1995	2005	Porsche
235-91748	Camshaft Position Sensor FSK	249,142	399	2008	2015	Subaru
235-91749	Crankshaft Position Sensor FSK	7,663	231	2008	2010	Porsche
235-91766	Crankshaft Position Sensor FSK	1,167	0	1984	1984	Porsche
235-91779	Crankshaft Position Sensor FSK	503	773	1990	1993	Volkswagen
235-91780	Camshaft Position Sensor FSK	281,940	540	2008	2020	Subaru
235-91790	Crankshaft Position Sensor FSK	408,434	11,787	2012	2017	Kia
235-91842	Crankshaft Position Sensor FSK	13,439	219	2004	2011	Porsche
235-91852	Crankshaft Position Sensor FSK	14,071	376	2009	2012	Porsche
235-91854	Camshaft Position Sensor FSK	543	0	1992	1997	Audi
235-91859	Camshaft Position Sensor FSK	94,809	157	2010	2012	Subaru
235-91860	Camshaft Position Sensor FSK	146,889	206	2010	2017	Subaru
235-91880	Camshaft Position Sensor FSK	30,002	5,288	1999	2002	Oldsmobile
235-91909	Crankshaft Position Sensor FSK	90,002	0	2014	2019	Jeep & Ram
235-91998	Crankshaft Position Sensor FSK	0	59,404	1994	1994	Nissan
235-92055	Crankshaft Position Sensor FSK	694	0	1994	1999	Ferrari
235-92056	Crankshaft Position Sensor FSK	11	0	1996	1998	Ferrari
235-92059	Crankshaft Position Sensor FSK	3,406	0	1990	1994	Porsche
235-92060	Crankshaft Position Sensor FSK	345	0	1989	1989	Porsche
235-92064	Crankshaft Position Sensor FSK	2,151	107	1997	1998	Audi
235-92093	Camshaft Position Sensor FSK	566,762	7,609	2012	2019	Hyundai & Kia
235-92101	Crankshaft Position Sensor FSK	394	0	1993	1995	Jaguar
240-91043	Vehicle Speed Sensor FSK	43,123	20,955	1995	2000	Mercury & Nissan
240-91058	Vehicle Speed Sensor FSK	1,991,711	466,612	1992	2001	Ford, Lincoln & Mercury
240-91063	Vehicle Speed Sensor FSK	2,340,481	154,147	2003	2012	Chrysler, Dodge, Jeep, Mitsubishi & Ram
240-91068	Vehicle Speed Sensor FSK	1,616,078	254,079	1997	2011	Ford & Mercury
240-91073	Vehicle Speed Sensor FSK	114,874	9,191	2004	2009	Chevrolet & Pontiac
240-91077	Vehicle Speed Sensor FSK	45,850	82,165	1995	2002	Ford & Mercury
240-91078	Vehicle Speed Sensor FSK	915,113	106,271	1999	2008	Ford, Mazda & Mercury
240-91090	Vehicle Speed Sensor FSK	235,760	187,543	1995	2000	Ford & Mercury
240-91091	Vehicle Speed Sensor FSK	211,577	107,134	1995	2002	Ford, Lincoln & Mercury
240-91103	Vehicle Speed Sensor FSK	25,800	27,367	1995	1999	Chrysler, Dodge, Eagle & Mitsubishi
240-91125	Vehicle Speed Sensor FSK	2,705,095	285,999	1997	2005	Ford & Lincoln
240-91128	Vehicle Speed Sensor FSK	2,216,594	230,407	1999	2014	Ford
240-91133	Vehicle Speed Sensor FSK	708,909	33,287	1999	2004	Ford
240-91147	Vehicle Speed Sensor FSK	3,022,587	51,610	2007	2019	Chrysler, Dodge & Ram
240-91159	Vehicle Speed Sensor FSK	56,058	77,737	2009	2011	Chevrolet & Pontiac

MAY 2021

Part #	Description - EN	US VIO	MX VIO	Start	End	Make
242-1204	Knock Sensor	769,395	95,327	2002	2010	Ford, Mazda & Mercury
242-91016	Knock Sensor FSK	311,588	84,487	1987	1995	Buick, Cadillac, Chevrolet, GMC, Oldsmobile & Pontiac
242-91017	Knock Sensor FSK	124,621	98,612	1981	1995	Buick, Cadillac, Chevrolet, Oldsmobile & Pontiac
242-91018	Knock Sensor FSK	723,341	62,757	1981	2002	Buick, Cadillac, Chevrolet, GMC, Isuzu, Oldsmobile & Pontiac
242-91019	Knock Sensor FSK	17,594	8,905	1995	1995	Buick, Chevrolet, Oldsmobile & Pontiac
242-91022	Knock Sensor FSK	717,499	125,978	1996	2001	Chevrolet, GMC, Isuzu & Oldsmobile
242-91023	Knock Sensor FSK	511,985	158,386	1990	1997	Cadillac, Chevrolet, GMC & Pontiac
242-91024	Knock Sensor FSK	443,674	618,714	1987	2015	Infiniti, Mercury & Nissan
242-91026	Knock Sensor FSK	53,155	84,731	1999	2001	Volkswagen
242-91027	Knock Sensor FSK	775,821	34,458	1995	2019	BMW, Kia, Mini, Porsche & Saab
242-91031	Knock Sensor FSK	63,736	24,663	1992	1995	Chevrolet & GMC
242-91032	Knock Sensor FSK	78,264	36,190	1992	1996	Chevrolet, GMC & Oldsmobile
242-91034	Knock Sensor FSK	1,910,043	338,469	1985	2002	Buick, Cadillac, Chevrolet, GMC, Oldsmobile & Pontiac
242-91039	Knock Sensor FSK	5,329,695	208,628	1998	2007	Buick, Cadillac, Chevrolet, GMC, Hummer, Isuzu & Pontiac
242-91047	Knock Sensor FSK	1,076,217	88,799	2002	2013	Chrysler, Dodge, Jeep, Mitsubishi & Ram
242-91050	Knock Sensor FSK	2,705,811	410,010	2003	2019	Infiniti, Nissan & Smart
242-91051	Knock Sensor FSK	640,369	74,209	2000	2005	Cadillac, Chevrolet, GMC, Oldsmobile & Saturn
242-91055	Knock Sensor FSK	8,644,875	563,542	2003	2019	Chrysler, Dodge, Fiat, Jeep, Ram & SRT
242-91061	Knock Sensor FSK	967,080	61,068	1998	2010	Chrysler & Dodge
242-91080	Knock Sensor FSK	54,277	6,304	1996	2000	Chevrolet & GMC
242-91100	Knock Sensor FSK	7,636		2000	2002	Hyundai
242-91111	Knock Sensor FSK	349,101		2003	2010	Hyundai & Kia
243-1001	Flex Fuel Sensor	1,884,599	76,892	2000	2005	Chevrolet & GMC
243-1004	Flex Fuel Sensor	445,094	4,852	2011	2018	Buick, Chevrolet & GMC
250-24119	O2 Sensor OE	0	31,193	2004	2014	Chevrolet & Fiat
250-241256	O2 Sensor OE	677,712	12,003	2017	2021	Honda
250-241266	O2 Sensor OE	352,277	7,426	2020	2020	Chevrolet & GMC
250-241268	O2 Sensor OE	386,775	7,426	2020	2020	Chevrolet & GMC
250-241269	O2 Sensor OE	126,183	2,015	2019	2020	Buick, Cadillac, Chevrolet & GMC
250-25155	O2 Sensor OE	9,412	0	2020	2020	Buick
255-1163	Fuel Pressure Regulator	452,050	660,432	1993	2015	Nissan
350-341032	O2 Sensor Aftermarket	126,305	1,643	2015	2020	Volvo
350-34351	O2 Sensor Aftermarket	0	31,193	2004	2014	Chevrolet & Fiat
550-1000	Fuel Injector Throttle Body	12,111	1,127	1995	1997	Chevrolet & GMC
920-1090	Ignition Coil	134,009		2005	2010	Hyundai & Kia
920-1152	Ignition Coil	3,171		1995	1995	Land Rover
921-2296	Ignition Coil on Plug	816,306	1,747	2011	2020	Mercedes-Benz

Part #	Description - EN	US VIO	MX VIO	Start	End	Make
924-1485	Wire Set, TCP 12-CYL	2,077	269	1988	2001	BMW
924-1550	Wire Set, TCP 7mm 4-CYL Univ Mag	3,700,316	1,949,706	1960	2013	Alfa Romeo, American Motors, Asuna, Austin, Austin Healey, Buick, Cadillac, Checker, Chevrolet, Chrysler, Daewoo, Daihatsu, Dodge, Eagle, Fiat, Ford, Geo, GMC, Honda, Hyundai, International, Isuzu, Jeep, Kia, Lada, Lancia, Mazda, Mercury, Merkur, Mini, Mitsubishi, Nissan, Oldsmobile, Opel, Peugeot, Plymouth, Pontiac, Renault, Saab, Saturn, Subaru, Suzuki, Toyota, Triumph, Volvo & Yugo
924-1551	Wire Set, TCP 7mm 4-Cyl Univ Cu	144,547	272,476	1960	2005	Audi, Porsche & Volkswagen
924-1552	Wire Set, TCP 7mm 8-Cyl Univ Mag	11,010,594	1,433,342	1957	2019	American Motors, Austin Healey, Buick, Cadillac, Checker, Chevrolet, Chrysler, DeLorean, Dodge, Eagle, Ford, GMC, Hyundai, International, Isuzu, Jeep, Mazda, Mercury, Mitsubishi, Nissan, Oldsmobile, Peugeot, Plymouth, Pontiac, Saturn, Studebaker, Subaru, Toyota, Triumph, Volkswagen & Volvo
924-1553	Wire Set, TCP 7mm 8-Cyl Univ Mag	12,271,198	996,948	1958	2015	American Motors, Buick, Cadillac, Chevrolet, Chrysler, DeTomaso, Dodge, Ford, GMC, Hummer, International, Jaguar, Jeep, Land Rover, Lincoln, Mazda, Mercury, Nissan, Oldsmobile, Plymouth, Pontiac, Ram, Saab, Studebaker, Sunbeam, Toyota & Triumph
924-1554	Wire Set, TCP 7mm 8-Cyl Univ Mag	2,817,771	408,032	1958	2003	AM General, Buick, Cadillac, Checker, Chevrolet, Chrysler, Dodge, Ford, GMC, Mercury, Oldsmobile, Plymouth & Pontiac
924-1980	Wire Set, TCP 7mm 4-Cyl	11,597		1997	1997	Subaru