

Ignition Coil Sets

2 NEW SKUs



Walker # 920-1061-8

2005-2020

Buick, Cadillac, Chevrolet, GMC,
Hummer, Isuzu, Pontiac & Saab

US VIO: 6,948,510

MX VIO: 116,187

Ignition Coil-On-Plug Sets

24 NEW SKUs



Walker # 921-2107-4

2005-2020

Infiniti & Nissan

US VIO: 6,766,677

MX VIO: 687,571

Ignition Coil-On-Plugs

12 NEW SKUs



Walker # 921-2314

2016-2020

Lexus & Toyota

US VIO: 1,680,951

MX VIO: 17,065

Manifold Absolute Pressure Sensors

5 NEW SKUs



Walker # 225-1308

2012-2020

Ford & Lincoln

US VIO: 1,099,422

MX VIO: 1,524

Ignition Knock Sensors

2 NEW SKUs



Walker # 242-1271
2002-2006
Hyundai & Kia
US VIO: 139,444

O2 Sensor - OE

1 NEW SKU



Walker # 250-241277
2015-2020
Genesis & Hyundai
US VIO: 87,746

Mass Air Flow Sensors, Sensor Only

2 NEW SKUs



Walker # 245-1365
2012-2017
Land Rover
US VIO: 81,021
MX VIO: 2,017

O2 Sensors - Replacement

2 NEW SKUs



Walker # 350-35135
2019-2020
Audi
US VIO: 69,095
MX VIO: 1,816

Throttle Position Sensors

3 NEW SKUs



Walker # 200-1426
2012-2015
Mazda
US VIO: 24,460
MX VIO: 27,594

Variable Valve Timing Solenoid

1 NEW SKU



Walker # 590-1293
2009-2012
Audi & Volkswagen
US VIO: 6,506
MX VIO: 241

OCTOBER 2021

PART #	DESCRIPTION - EN	US VIO	MX VIO	START	END	MAKE
200-1378	THROTTLE POSITION SENSOR	2,314		1999	2001	Hyundai
200-1380	THROTTLE POSITION SENSOR	1,817		1985	2001	Jaguar & Subaru
200-1426	THROTTLE POSITION SENSOR	24,460	27,594	2012	2015	Mazda
225-1114	MAP SENSOR	2,034		1989	1991	Mazda
225-1162	MAP SENSOR	945		1997	1997	Mitsubishi
225-1308	MAP SENSOR	1,099,422	1,524	2012	2020	Ford & Lincoln
225-1370	MAP SENSOR	2,987		1989	1990	Geo & Suzuki
225-1399	MAP SENSOR	173,157	4,699	2018	2020	Ford
242-1270	KNOCK SENSOR	1,694		2001	2001	Hyundai
242-1271	KNOCK SENSOR	139,444		2002	2006	Hyundai & Kia
245-1365	MASS AIR FLOW SENSOR, Sensor Only	81,021	2,017	2012	2017	Land Rover
245-2204	MASS AIR FLOW SENSOR, Sensor Only	5,183	306	2003	2004	Mercury
250-241277	O2 SENSOR, 4-W DIRECT FIT	87,746		2015	2020	Genesis, Hyundai
350-35129	O2 SENSOR, 5-W WIDEBAND DIRECT FIT	57,061	8,029	2019	2020	Audi & Volkswagen
350-35135	O2 SENSOR, 5-W WIDEBAND DIRECT FIT	69,095	1,816	2019	2020	Audi
590-1293	Variable Valve Timing Solenoid	6,506	241	2009	2012	Audi & Volkswagen
920-1021-8	IGNITION, COIL SET	257,056	23,776	1997	2005	Cadillac, Chevrolet, GMC & Pontiac
920-1061-8	IGNITION, COIL SET	6,948,510	116,187	2005	2020	Buick, Cadillac, Chevrolet, GMC, Hummer, Isuzu, Pontiac & Saab
921-2001-8	IGNITION, COIL ON PLUG SET	383,708	31,892	1997	2014	Ford, Lincoln & Mercury
921-2002-8	IGNITION, COIL ON PLUG SET	1,052,712	64,212	1999	2007	Chrysler, Dodge, Jeep & Mitsubishi
921-2003-6	IGNITION, COIL ON PLUG SET	796,896	47,602	2002	2008	Buick, Chevrolet, GMC, Isuzu, Oldsmobile & Saab
921-2005-8	IGNITION, COIL ON PLUG SET	4,217,594	344,701	1997	2016	Ford, Lincoln & Mercury
921-2006-8	IGNITION, COIL ON PLUG SET	92,562	8,234	1999	2006	Ford, Jaguar & Lincoln
921-2007-8	IGNITION, COIL ON PLUG SET	1,390,062	84,476	2004	2008	Ford, Lincoln & Mercury
921-2009-3	IGNITION, COIL ON PLUG SET	767,100	10,690	1995	2004	Toyota
921-2015-6	IGNITION, COIL ON PLUG SET	832,615	16,057	1999	2006	Lexus & Toyota
921-2023-6	IGNITION, COIL ON PLUG SET	1,606,703	61,763	2002	2019	Infiniti, Nissan & Suzuki
921-2024-4	IGNITION, COIL ON PLUG SET	419,083	131,872	2002	2008	Nissan
921-2029-4	IGNITION, COIL ON PLUG SET	231,621		2006	2011	Hyundai & Kia
921-2049-4	IGNITION, COIL ON PLUG SET	199,375	121,720	2002	2006	Nissan
921-2056-6	IGNITION, COIL ON PLUG SET	1,408,507	52,694	2003	2015	Toyota
921-2065-4	IGNITION, COIL ON PLUG SET	1,135,534	65,189	2003	2013	Ford, Mazda & Mercury
921-2066-8	IGNITION, COIL ON PLUG SET	845,283	48,823	2008	2014	Ford, Lincoln & Mercury
921-2075-6	IGNITION, COIL ON PLUG SET	412,136	15,592	2004	2009	Buick, Cadillac, Chevrolet, GMC, Saab & Saturn
921-2083-3	IGNITION, COIL ON PLUG SET	80,559		2003	2006	Kia
921-2084-6	IGNITION, COIL ON PLUG SET	56,035	1,839	2002	2008	Jaguar
921-2089-6	IGNITION, COIL ON PLUG SET	5,717,849	121,822	2005	2021	Lexus & Toyota
921-2091-6	IGNITION, COIL ON PLUG SET	405,773	7,321	2006	2009	Buick, Chevrolet, GMC, Isuzu & Saab
921-2094-6	IGNITION, COIL ON PLUG SET	644,236	17,773	2004	2008	Lexus & Toyota
921-2107-4	IGNITION, COIL ON PLUG SET	6,766,677	687,571	2005	2020	Infiniti & Nissan
921-2110-4	IGNITION, COIL ON PLUG SET	1,137,349	220,531	2005	2018	Audi & Volkswagen
921-2126-4	IGNITION, COIL ON PLUG SET	4,225,832	89,306	2000	2021	Chevrolet, Lexus, Pontiac, Scion & Toyota
921-2145	IGNITION, COIL ON PLUG	140,966	14,753	2000	2003	Cadillac & Oldsmobile
921-2281	IGNITION, COIL ON PLUG	77,593		2013	2016	Hyundai & Kia
921-2286	IGNITION, COIL ON PLUG	404,799	32,628	2013	2019	Audi & Volkswagen
921-2305	IGNITION, COIL ON PLUG	5,130	610	2015	2018	Audi
921-2314	IGNITION, COIL ON PLUG	1,680,951	17,065	2016	2020	Lexus & Toyota
921-2319	IGNITION, COIL ON PLUG	259,562	5,738	2001	2016	BMW & Mini
921-2326	IGNITION, COIL ON PLUG	488,270	27,912	2016	2020	Toyota
921-2327	IGNITION, COIL ON PLUG	83,678		2016	2019	Nissan
921-2328	IGNITION, COIL ON PLUG	83,678		2016	2019	Nissan
921-2343	IGNITION, COIL ON PLUG	534,708	7,531	2016	2018	Buick, Cadillac, Chevrolet & GMC
921-2347	IGNITION, COIL ON PLUG	697,702	33,967	2017	2020	BMW & Mini
921-2348	IGNITION, COIL ON PLUG	18,769	8,941	2016	2016	Chevrolet