



Introducing....New Products

Carburetor & Fuel Pump Repair Kits




Walker Products, Inc. has released 12 new fuel pump repair kits for popular Mercury marine engines and 3 new carburetor repair kits. The new carburetor repair kit (778-624) fits Onan marine and agricultural engines.

Recently we have tooled and manufactured over 250 new components, gaskets and repair kits for these markets. They are:

Fuel Pump Repair Kits


16062



Replaces Mercury OEM #1399-5135
Fits applications 7.5, 9.8 hp

HP	Year - S/N	Carb Model
7.5 hp	All	BB-5A, BB-5B, BB5C, BB-5D, BB-5A, BB-5B,
7.5 hp	All	BB5C, BB-5D, BB7A, BB-7C
9.8 hp	1985-72	BB-1B, BB-1C, BB-3A, BB-3B; BB-3C,
9.8 hp	1985-72	BB-6A, BB-6C


16063



Replaces Mercury OEM #1399-5198
Fits applications 20, 50 hp OB

HP	Year - S/N	Carb Model
20 hp	1980-73	BA-1A, BA-2A, BA-2C, BA-2D, BA-2E
50 hp	1985-76	BA-3B, BA-3C, BA-3D
50 (4cyl)	1986-Up	BA-3A, 3B, 3C, 3D, 4A

16064



Replaces Mercury OEM 55278A5
Fits applications 75, 80, 85 hp OB

HP	Beginning	Ending
75 (4 cyl.)	6432901	C099999
80 hp	2559001	2670574
80 hp	4831999	6432900
85 hp	3493913	4831998


YOUR FIRST CHOICE IN QUALITY PRODUCTS



Walker
walkerproducts.com

Fuel Pump Repair Kits (cont'd)


16065



Replaces Mercury OEM 89031A2
Fits early V-6 OB

HP	Beginning	Ending
V-150 XR2	ALL	ALL
V-200	4839034	6073191
V-300/3.4L	5611648	& UP


16066



Replaces Mercury OEM 89031A3
Fits 90, 115, 140, in line 6 cyl
(later models)

HP	Beginning	Ending
115 (6 cyl.)	5314656	& UP


16067



Replaces Mercury OEM 89031A4
Fits V-6 OB

HP	Beginning	Ending
V-200	6357230	6625220


16068



Replaces Mercury OEM 90363A1
Fits 200 hp, V-6

HP	Beginning	Ending
V-200	6073192	6357229
V-225	5628028	& UP

16069



Replaces Mercury OEM 89031A1
Fits 90, 115, 140, in line (6 cyl)


HP	Beginning	Ending
90 (6 cyl.)	5299506	& UP
140 hp	4865678	5327662

YOUR FIRST CHOICE IN QUALITY PRODUCTS



Fuel Pump Repair Kits (cont'd)

16070




Replaces Mercury OEM 42909A4
Fits 75, 80, 90, 100, 115, hp
(early models)

HP	Beginning	Ending
70 hp	A996142	& UP
75 (3 cyl.)	A996142	D283221
80 (3 cyl.)	A966142	& UP
90 (3 cyl.)	A996142	D283221
100 (4 cyl.)	B209468	& UP
115 (4 cyl.)	B209468	& UP

16071

w/Filter Screen




Replaces Mercury OEM 89031A2
Fits early V-6 OB

HP	Beginning	Ending
V-150 XR2	ALL	ALL
V-200	4839034	6073191
V-300/3.4L	5611648	& UP

16072

w/Filter Screen




Replaces Mercury OEM 89031A3
Fits 90, 115, 140, in line 6 cyl
(later models)

HP	Beginning	Ending
115 (6 cyl.)	5314656	& UP

16073

w/Filter Screen




Replaces Mercury OEM 89031A4
Fits V-6 OB

HP	Beginning	Ending
V-200	6357230	& UP

16074

w/Filter Screen



Replaces Mercury OEM 90363A1
Fits 200 hp, V-6


HP	Beginning	Ending
V-200	6073192	6357229
V-225	5628028	& UP



Walker
walkerproducts.com

Fuel Pump Repair Kits (cont'd)

16075
w/Filter Screen




Replaces Mercury OEM 89031A1
Fits 90, 115, 140, in line (6 cyl)

HP	Beginning	Ending
90 (6 cyl.)	5299506	& UP
140 hp	4865678	5327662

Carburetor Repair Kit

778-624



Replaces Onan OEM 142-0571
Fits Onan BF, BG, B43M, B48M

HP	Beginning	Ending
All	All	BF, BG, B43M, B48M



WALKER PRODUCTS

525 WEST CONGRESS STREET • PACIFIC, MO 63069

Corporate Office: 636-257-2400 • Fax: 636-257-6211

Customer Service: 636-257-1700 • Technical Support: 844-252-0114

www.walkerproducts.com

YOUR FIRST CHOICE IN QUALITY PRODUCTS