



# **FORD 7.3 GODZILLA**

## **PERFORMANCE IGNITION WIRES**

**Built for the Ford 7.3L V8 Gas Platform (2020+)**



**924-2127**

**924-2102**

### **FEATURES & BENEFITS:**

- **Upgraded Aluminum Heat Shields & Silicone Wire** protect against prolonged under-hood temperatures
- **Fiberglass Insulator Socks & Boot Protectors** rated to 1,200°F for extreme heat protection
- **OE Problem Solver** eliminates common factory heat failures for improved reliability
- **Extended Service Life** delivers long-term performance in demanding environments
- **Also available with a white insulator sock**




WALKER PRODUCTS, INC. • 525 WEST CONGRESS STREET • PACIFIC, MO 63069 • [www.walkerproducts.com](http://www.walkerproducts.com)  
U.S. Corporate Office: 636-257-2400 • Fax: 636-257-6211 • Customer Service: 636-257-1700 • Technical Support: 844-252-0114  
U.K. Sales Office and Distribution Center: +44-121-459-8006 • [saleseurope@walkerproducts.com](mailto:saleseurope@walkerproducts.com)  
Oficinas para Mexico: +52-72-2402-2167 • Soporte tecnico y servicio al cliente en Mexico: +52-72-2207-8957

© 2025 Walker Products, Inc. All rights reserved.

# FAQs

## Ford 7.3 Godzilla Performance Ignition Wires



### Q: Why replace the OE ignition wires?

**A:** Factory wires are prone to heat damage in the 7.3L engine bay, leading to misfires, reduced performance, and premature failure.

### Q: How does this design solve heat issues?

**A:** Upgraded aluminum heat shields, high-temp silicone wire, and fiberglass insulator socks protect against prolonged exposure to extreme under-hood heat — up to 1,200°F.

### Q: Will these wires improve performance?

**A:** Yes — consistent spark delivery helps maintain peak horsepower, torque, and fuel efficiency under heavy load or towing conditions.

### Q: Are these a direct replacement?

**A:** Yes — engineered for OE fitment, no modifications needed.

### Q: Where are they made?

**A:** Proudly made in the USA with premium-grade materials for long-lasting reliability.

**Fiberglass Insulator Socks  
Cover the Entire Heat Shield at the Spark Plug**

### TECH INSIGHT

Built for the Heat — The Ford 7.3L “Godzilla” V8 produces intense under-hood temperatures, especially during towing or heavy-duty use. OE wires often fail when exposed to this prolonged heat. Walker’s upgraded design combats this with:

- Aluminum Heat Shields for superior thermal deflection
- High-Temp Silicone Wire for consistent electrical performance
- Fiberglass Insulator Socks & Boot Protectors rated to 1,200°F for maximum durability
- This combination delivers reliable spark energy, prevents heat-related breakdowns, and extends service life, even in the harshest conditions.

