

Ignition Coils

5 NEW SKUs



Walker # 920-1020-8

1999-2007

Buick, Cadillac, Chevrolet, GMC, Hummer & Isuzu

US VIO: 4,952,526

MX VIO: 193,843

Fuel Injector Seal Kit

1 NEW SKU



Walker # 17129

2006-2009

Buick, Chevrolet, GMC,
Hummer, Pontiac, Saab
& Saturn

US VIO: 2,833,492

MX VIO: 63,994

Vehicle Speed Sensors

3 NEW SKUs



Walker # 240-1141

2004-2013

Lexus & Toyota

US VIO: 2,243,757

MX VIO: 52,747

Throttle Position Sensor FSK®

12 NEW SKUs



Walker # 200-91238

1996-2006

Pontiac & Toyota

US VIO: 824,504

MX VIO: 14,762

Camshaft-Crankshaft Position Sensors

3 NEW SKUs



Walker # 235-1248

2017-2020

Hyundai & Kia

US VIO: 110,573

MX VIO: 3,938

NOVEMBER 2021

PART #	DESCRIPTION - EN	US VIO	MX VIO	START	END	MAKE
17129	Fuel Injector Seal Kit	2,833,492	63,994	2006	2019	Buick, Chevrolet, GMC, Hummer, Pontiac, Saab & Saturn
200-91097	TPS FSK	8,702	63,080	1995	1999	Dodge & Plymouth
200-91238	TPS FSK	824,504	14,762	1996	2006	Pontiac & Toyota
200-91317	TPS FSK	5,211	2,989	1998	2001	Chevrolet & Suzuki
200-91358	TPS FSK	85,553	109,607	2001	2006	Chrysler & Dodge
200-91366	TPS FSK	681		2000	2000	Isuzu
200-91377	TPS FSK	14,469		1985	1986	Buick, Chevrolet, GMC, Oldsmobile & Pontiac
200-91392	TPS FSK	2,047		1993	1995	Volkswagen
200-91401	TPS FSK	3,124		1985	1985	Chevrolet & Pontiac
200-91402	TPS FSK	35,372	739	1990	1993	Chevrolet, GMC & Pontiac
200-91416	Throttle Position Sensor FSK	2,245		1985	1985	Buick
200-91437	Throttle Position Sensor FSK	4,575		1985	1986	Buick, Cadillac, Chevrolet, Oldsmobile & Pontiac
200-91459	Throttle Position Sensor FSK	25,793		1988	1990	Cadillac, Chevrolet, GMC, Oldsmobile & Pontiac
235-1248	Crankshaft Position Sensor	110,573	3,938	2017	2020	Hyundai & Kia
235-1289	Camshaft Position Sensor	52,342	2,092	2019	2020	Hyundai & Kia
235-2354	Crankshaft Position Sensor	31,406		2020	2020	Hyundai
240-1139	VEHICLE SPEED SENSOR	227,265	10,587	2004	2009	Nissan
240-1141	VEHICLE SPEED SENSOR	2,243,757	52,747	2004	2013	Lexus & Toyota
240-1142	VEHICLE SPEED SENSOR	248,326	20,084	2006	2018	Audi & Volkswagen
920-1005-3	IGNITION, COIL SET	3,151,964	620,831	1986	2009	Buick, Cadillac, Chevrolet, Honda, Isuzu, Oldsmobile & Pontiac
920-1020-8	IGNITION, COIL SET	4,952,526	193,843	1999	2007	Buick, Cadillac, Chevrolet, GMC, Hummer & Isuzu
921-2010-8	IGNITION, COIL ON PLUG SET	1,193,429	22,386	1998	2010	Lexus & Toyota
921-2013-4	IGNITION, COIL ON PLUG SET	1,368,096	53,776	2000	2008	Toyota
921-2248	IGNITION, COIL ON PLUG	2,525		2004	2004	Isuzu